

ANNUAL SURVEYS.

22964 34952

No. X Survey held at London Date, first Survey Feb 25 Last Survey March 17 1879
 No. in on the BK Ellora Master Ballingale
 Reg. Book. 551 Tonnage 131 Built at Glasgow When built 1876 5M
 By whom built Barclay Owners Foley & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 19335 Port of Iron

Classed 100 A 8.77
 Years assigned. Character in Register Book.

Present Condition of the					
Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stemson	"	"	Windlass and Capstan
Comings	"	Transoms, Pointers, and Crutches	"	"	Pumps
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Boats
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Masts, Yards, &c.
Planksheers	"	Keelsons	"	"	Condition, how ascertained
Sheerstrakes	"	Clamps and Shelves	"	"	Sails
Topsides	"	Ceiling	"	"	Anchors, No. of <u>3</u> <u>Pro. St. V. Rdp.</u>
Wales	"	Rudder	"	"	Cables
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>now</u>			Hawsers and Warps
Engine Room Skylights	<u>Good</u>	Caulking of			Standing and Running Rigging
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>		
General Observations, Opinion as to Class, &c.	<u>Bottom Coated</u>				

She is now in good condition and entitled to remain as classed.

Committee's Minute 21st March, 1879.

Character assigned 100 A

Samhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. X Survey held at London Date, first Survey March 10 Last Survey March 12 1879
 No. in on the SS Tenedos Master Harris
 Reg. Book. 135 Tonnage 253 Built at Glasgow When built 1873 11M
 By whom built Ln & Gls Co. Owners Globe Steam Ship Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 21759 Port of Iron

Classed 100 A 8.78
 Years assigned. Character in Register Book.

Present Condition of the					
Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stemson	"	"	Windlass and Capstan
Comings	"	Transoms, Pointers, and Crutches	"	"	Pumps
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Boats
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Masts, Yards, &c.
Planksheers	"	Keelsons	"	"	Condition, how ascertained
Sheerstrakes	"	Clamps and Shelves	"	"	Sails
Topsides	"	Ceiling	"	"	Anchors, No. of <u>3</u> <u>Pro. St. V. Rdp.</u>
Wales	"	Rudder	"	"	Cables
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>now</u>			Hawsers and Warps
Engine Room Skylights	<u>Good</u>	Caulking of			Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>		
General Observations, Opinion as to Class, &c.	<u>Bottom Coated</u>				

She is now in good condition and entitled to remain as classed.

Committee's Minute 21st March, 1879.

Character assigned 100 A

Samhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18