

ANNUAL SURVEYS.

23004

No. 2585 Survey held at Belfast Date, first Survey ✓ Last Survey 13th March 1879
 No. in on the S. "North Wales" Master J. Owens
 Reg. Book. 363 Tonnage 196.1157.1019 Built at Hull When built 1875-12
 By whom built Humphrys Owners H. Roberts
 Port belonging to London Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock dry dock

Last Survey, No. 16306 Port of Iron Classed 100 A.I.
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways — Breasthooks and Stemson —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons Good
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wales — Rudder —
 Plank (Bottom) and Counter — Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers — Cargo and Main Hatchways Good Hatches —

General Observations, Opinion as to Class, &c.
Surveyed in ballast and with a portion of cargo on board. Notice was given to the owner that S.S. No. 1 should be complied with during the year.
Vessel placed in dry dock, bottom & keel examined, cleaned and painted.
She appeared to be in good condition and is eligible in my opinion to remain classed 100 A.I.

Committee's Minute 21st March 1879
 Character assigned 100 A.I.
J.W. Scullard
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18


No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.

 Committee's Minute 18
 Character assigned

 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



© 2019

Lloyd's Register Foundation

1804483-0288