

REPORT of SURVEY for REPAIRS, &c.

No. 23008
No. in Reg. Book. 361 on the S. S. "Petrarch"
Survey held at London Date, first Survey 12th 16th Last Survey 14th March 1879
Master R. John.
TONNAGE under Tonnage Deck 1444
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 1693
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St^rmer, cut on Bm. 1297
Built at S. Shields When built 1877 9
Owners M^r Andrew & Co. Port belonging to London
Residence
By whom built Readhead Destined Voyage
If Surveyed Afloat or in Dry Dock Parkers by Lock Milwall.
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
Last Survey, No. 20862 Port Iron
Classed 100 A. 1.
5-78.

REPAIRS, OR EXAMINATION AS PER RULE Damage Repairs &c.
Bottom examined, one badly Indented
topside plate taken out rolled and replaced, one broken
frame partly renewed with efficient joint covers, and cracked
frame strengthened with an extra reverse frame, bottom
cleaned and coated with Paint and Tallow.

Present Condition of the
Decks Rivets
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. This vessel is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Entry Fee ... £ 1 : 5 : received by me, J. B. 25th March 1879
Certificate (if required) ... £
(Travelling Expenses, if any, £)
Committee's Minute 25th March 1879
Character assigned 100 F
J. B. W.