

23055
ANNUAL SURVEYS.

152 1110
No. 409 Survey held at Dublin. Date, first Survey Rev 27/3/79 Last Survey 7 March 1879
No. in on the Ship Lord Cairns Master J Dunn
Reg. Book. 670 Tonnage 1311 Built at Belfast When built 1877 5th mo
By whom built Harland Wolff & Co Owners J Dixon & Co
Port belonging to Belfast Destined Voyage Philadelphia
If Surveyed Afloat or in Dry Dock In dry Dock

Last Survey, No. 20814 Port of Iron Classed 100. A1
Present Condition of the
Decks all good
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plating
Plank (Bottom) and Counter
Engine Room Skylights
Coal Bunker, Openings, Lids, &c.
General Observations, Opinion as to Class, &c.
Treenails Rivets
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places good
Keelsons
Clamps and Shells
Ceiling
Rudder In good working order
Copper or Y.M. Coated When put on now
Caulking of
Bottom, Deck, & Waterways good
Windlass and Capstan Both good
Pumps 2 M Comp good
Boats 4 good
Masts, Yards, &c. appear good
Condition, how ascertained Inspection & Inquiry
Sails 2 suits good
Anchors, No. of 3 B. 10. 2 K
Cables 270 fms
Hawsers and Warps 4 good
Standing and Running Rigging good
Scuppers uff. Cargo and Main Hatchways good Hatches good

This vessel has been placed on blocks in Dry Dock...
Her Keel & bottom examined & found in good condition
Bottom has been scraped clean & coated double with
Compo paint - I consider her to be in a good & efficient
state of repair & eligible to remain as classed
Committee's Minute 28th March, 1879.
Character assigned 100A1
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 57 Mar 1879
Surveyors

No. Survey held at Date, first Survey Last Survey 1879
No. in on the Master
Reg. Book. Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
Present Condition of the
Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
Engine Room Skylights
Coal Bunkers, Openings, Lids, &c.
General Observations, Opinion as to Class, &c.
Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shells
Ceiling
Rudder
Copper or Y.M. When put on
Caulking of
Bottom, Deck, & Waterways
Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging
Scuppers
Cargo and Main Hatchways
Hatches

Committee's Minute
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid
Lloyd's Register
Foundation
IRON483-0357