

ANNUAL SURVEYS.

No. 4496 Survey held at Newport Date, first Survey 11/3/79 Last Survey 18/4/79
 No. in on the Netley Abbey Master Pyman, Watson & Co
 Reg. Book. 1113 Tonnage 1725 Built at W. Hartlepool When built 1848
 Sup By whom built Gray Owners Pyman, Watson & Co
 Port belonging to Cardiff Destined Voyage Alexandria Dry Dock
 If Surveyed Afloat & in Dry Dock

Last Survey, No. 100.A.1 Port of Cardiff Classed 100.A.1
 Present Condition of the
 Decks Waterways Comings Upper Deck Beams & Fastenings Lower Deck Beams & Fastenings Planksheers Sheerstrakes Topsides Wales Plank (Bottom) and Counter
Treenails Breasthooks and Stemson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Ditto ditto at other places Keelsons Clamps and Shells Ceiling Rudder Copper or Y.M. When put on Caulking of Bottom, Deck, & Waterways Windlass and Capstan Pumps Boats Masts, Yards, &c. Condition, how ascertained Sails Anchor, No. of Cables Hawsers and Warps Standing and Running Rigging
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

This vessel having received damage at Bermuda, was placed in Dry Dock at Newport for examination, but the owners having decided to send her to West Hartlepool (whither she has since proceeded) for repairs. In order to prevent delay, the water was let into the dock for the purpose of floating her, before I was able to see her bottom.

Committee's Minute 18 Character assigned 18
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. 18 Survey held at 18 Date, first Survey 18 Last Survey 18
 No. in on the 18 Master 18
 Reg. Book. 18 Tonnage 18 Built at 18 When built 18
 By whom built 18 Owners 18
 Port belonging to 18 Destined Voyage 18
 If Surveyed Afloat or in Dry Dock 18

Last Survey, No. 18 Port of 18 Classed 18
 Present Condition of the
 Decks Waterways Comings Upper Deck Beams & Fastenings Lower Deck Beams & Fastenings Planksheers Sheerstrakes Topsides Wales Plank (Bottom) and Counter
Treenails Breasthooks and Stemson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Ditto ditto at other places Keelsons Clamps and Shells Ceiling Rudder Copper or Y.M. When put on Caulking of Bottom, Deck, & Waterways Windlass and Capstan Pumps Boats Masts, Yards, &c. Condition, how ascertained Sails Anchor, No. of Cables Hawsers and Warps Standing and Running Rigging
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18 Character assigned 18
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

Netty Atkey



© 2019

Lloyd's Register
Foundation