

120483-0401

ANNUAL SURVEYS.

23086

No. Survey held at London Date, first Survey 13.3.79 Last Survey 1.4.79 Recd 5.4.79
 No. in on the S. S. "Dacia" Master Hayward
 Reg. Book. 7 Tonnage 1473 Built at Sunderland When built 1867-11 mo
1856 By whom built Laing Owners Ind. Rub. Gut. Per. & L.L. Wks Co. (Lm.)
1252 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Millwall Dry Dock & afloat

Last Survey, No. 19698 Port of Iron

Present Condition of the
Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plating (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Rivets
Transoms

Breasthooks and Stems

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto

Keelsons

Stringers
Clamps and Shells

Ceiling

Rudder

Copper or Y.M.

Caulking of

Bottom, Deck, & Waterways

where seen, good

good

good

good

good

good

good

good

good

good

good

good

S.S. h^o 2-75

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchor, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Classed B. 1.

11.77

good

good

good

good

From Sk Enquiry

well found

3 B, 1 S & 2 K.

said to be complete

good

good

Cargo and Main Hatchways good Hatches good

recoated with composition. Cement tested in several places in holds, where seen found in good condition & adhering to the iron. The vessel appears in good condition and eligible, in my opinion, to remain as classed.

Committee's Minute

Character assigned

8th April,

1879.

B. 1

TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18