

ANNUAL SURVEYS.

23088

No. 2642¹ Survey held at Liverpool Date, first Survey Mar 17th Last Survey Mar 20th 1879
 No. in on the Ship "Glenlyon" Master A Wood
 Reg. Book. 479 Tonnage 665 Built at Dundee When built 1868 - 7mo.
 By whom built Brown Owners W. O. Taylor & Co.
 Port belonging to Dundee Destined Voyage Siquique
 If Surveyed Afloat or in Dry Dock Sandon Dry Dock

Last Survey, No. 20960 Port of Iron Classed S.S. Ret N^o 2. 76. Years assigned. 5. 78. Character in Register Book. *AI
 Present Condition of the
 Decks Good Trunnails Rivets. Good S.S. Ret N^o 2. 76.
 Waterways 4 Breasthooks and Stenson 4 Windlass and Capstan Good
 Comings 4 Transoms, Pointers, and Crutches 4 Pumps 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4 Boats 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4 Masts, Yards, &c. 4
 Planksheers 4 Keelsons 4 Condition, how ascertained from on board Good
 Sheerstrakes 4 Clamps and Shells 4 Sails 4
 Topsides 4 Ceiling 4 Anchors, No. of 4
 Wales 4 Rudder 4 Cables part seen and
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 68. Hawsers and Warps 4
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool April 8th 1879. J. Shilston.
 Character assigned *AI. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

No. ✓ Survey held at Liverpool Date, first Survey Mar 22nd Last Survey Mar 22nd 1879
 No. in on the Bark "Dumicker" Master J. Swan
 Reg. Book. 533 Tonnage 444 Built at Glasgow When built 1861 - 7mo.
 By whom built Stephen Owners J. Skinner & Co.
 Port belonging to Glasgow Destined Voyage Siquique
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock

Last Survey, No. 15906 Port of Iron Classed S.S. Ret N^o 1. 76. Years assigned. 3. 76. Character in Register Book. *AI
 Present Condition of the
 Decks Good Trunnails Rivets. Good S.S. Ret N^o 1. 76.
 Waterways 4 Breasthooks and Stenson 4 Windlass and Capstan Good
 Comings 4 Transoms, Pointers, and Crutches 4 Pumps 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4 Boats 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4 Masts, Yards, &c. 4
 Planksheers 4 Keelsons 4 Condition, how ascertained from on board Good
 Sheerstrakes 4 Clamps and Shells 4 Sails 4
 Topsides 4 Ceiling 4 Anchors, No. of 4
 Wales 4 Rudder 4 Cables part seen and
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 61 Hawsers and Warps 4
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool April 8th 1879. J. Shilston.
 Character assigned *AI. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

Glenlyon
Dumnick

26421.



© 2019

Lloyd's Register
Foundation