

ANNUAL SURVEYS.

No. 1176 Survey held at London Date, first Survey 13th March Last Survey 24th March 1879.
 No. in on the S. S. "Suez" Master G. R. Inck
 Reg. Book. 1176 Tonnage 1390 Built at Newcastle When built 1874 9th mo.
 By whom built Mitchell Owners Nelson, Donkin & Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock West India Dock.

Last Survey, No. X20642 Port of Iron

Present Condition of the Decks

Waterways	Good	Tronails	Rivets	Good where seen	Classed	Years assigned.	Character in Register Book.
Comings	"	Breasthooks and Stemson		do			100 A1
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches		do			3.78
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		do			S. S. Newc. No. 1-78
Planksheers	"	Ditto ditto at other places		do			Good
Sheerstrakes	"	Keelsons		do			Pumps
Topsides	"	Clamps and Shells		do			Boats 7 in number
Wales	"	Ceiling		do			Masts, Yards, &c.
Plank (Bottom) and Counter where seen	"	Rudder		do			Condition, how ascertained from deck & enquiry
Engine Room Skylights	good	Copper or F.M. Paint When put on		do			Sails well found
Coal Bunker, Openings, Lids, &c.	good	Caulking of		do			Anchors, No. of 3 B. 1st. 2 nd .
General Observations, Opinion as to Class, &c.		Bottom, Deck, & Waterways	good	do			Cables complete
		Scuppers	good	do			Hawsers and Warps
				do			Standing and Running Rigging
				do			Cargo and Main Hatchways
				do			Hatches

Renewed and bulwark plate on starb. quarter, repaired Rail, stringer plate & Deck house coaming on starb. quarter.

Surveyed with part of inward cargo in hold.

She appears now in good condition & is eligible in my opinion to remain as classed.

Committee's Minute 4th April 1879

Character assigned 100 A1 TJW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 59 Survey held at London Date, first Survey 23th March Last Survey 28th March 1879.
 No. in on the S. S. "Falcon" Master V. H. Kales
 Reg. Book. 59 Tonnage 389 Built at Newcastle When built 1876 1st mo.
 By whom built Mitchell Owners Gen. St. Nav. Company
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Gen. St. Nav. Comp^y. Dry Dock.

Last Survey, No. 20203 Port of Iron

Present Condition of the Decks

Waterways	Good	Tronails	Rivets	Good where seen	Classed	Years assigned.	Character in Register Book.
Comings	"	Breasthooks and Stemson		do			100 A1
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches		do			1.78
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		do			Good
Planksheers	"	Ditto ditto at other places		do			Pumps
Sheerstrakes	"	Keelsons		do			Boats 5 in number
Topsides	"	Clamps and Shells		do			Masts, Yards, &c.
Wales	"	Ceiling		do			Condition, how ascertained from deck & enquiry
Plank (Bottom) and Counter	"	Rudder	good	do			Sails well found
Engine Room Skylights	good	Copper or F.M. Paint When put on	now	do			Anchors, No. of 3 B. 1st. 2 nd .
Coal Bunkers, Openings, Lids, &c.	good	Caulking of		do			Cables complete
General Observations, Opinion as to Class, &c.		Bottom, Deck, & Waterways	good	do			Hawsers and Warps
		Scuppers	good	do			Standing and Running Rigging
				do			Cargo and Main Hatchways
				do			Hatches

Bottom cleaned & recoated with black varnish.

Surveyed with dunnage etc in hold.

She appears now in good condition & is eligible in my opinion to remain as classed.

Committee's Minute 4th April 1879

Character assigned 100 A1 TJW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18