

23260
REPORT of SURVEY for REPAIRS, &c.

No. 3209

No. in Reg. Book. Survey held at Aberdeen Date, first Survey April 15 Last Survey April 14 1879

Supplement 8 on the Benamain Master R. Russell

Official Number 34444
TONNAGE under Tonnage Deck 308
Ditto of Spar Deck, or Avoing Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 381
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as S^{er}-mer, cut on Bm. 244
Built at Aberdeen When built 1848
Owners J. A. Davidson Port belonging to Aberdeen
Residence Aberdeen
By whom built Hall, Russell, & Co Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock On the hard Aberdeen

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.

Last Survey, No. 22666 Port Iron Classed 100ct 1

REPAIRS, OR EXAMINATION AS PER RULE for Damage from striking the Quay. Both decks Sunderland. Renewed. Two fore hoods of outside plating. Straightened stem, rivets in floor plates, and breasthooks, and cement removed to renew shell plates.

Present Condition of the Decks Good
Waterways "
Comings "
Upper Deck Beams & Fastenings "
Lower Deck Beams & Fastenings "
Planksheers "
Sheerstrakes "
Topsides "
Wales "
Plank (Bottom) and Counter "
Twists Good
Treenails Good
Breasthooks and Stenson "
Transoms, Pointers, and Crutches "
Timbers of the Frame at the openings "
Ditto Ditto at other places "
Keelsons "
Clamps and Shelves "
Ceiling "
Rudder "
Copper When put on "
Caulking of Bottom, Deck, & Waterways Good
Windlass and Capstan Good
Pumps of iron efficient
Boats Two good
Masts, Yards, &c. "
Condition, how ascertained from examination of engine
Sails Good
Anchors No. of 3 Power 1 Steam 1 Keel
Cables Good
Hawsers and Warps 8 sufficient
Standing & Running Rigging "
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. This vessel has now been efficiently repaired, is in good condition and is eligible in my opinion to remain as Classed 100ct 1.

The Amount of Entry Fee ... £ : : received by me, J. W. Little
Special Damages £ 2 : 2 : 0 April 1879
Certificate (if required) ... £ : 5 : 0
(Travelling Expenses, if any, £ none)

Committee's Minute 29th April 1879

Character assigned 100ct 1
J. W. Little

Surveyor to Lloyd's Register of British and Foreign Shipping.

120434-0114