

ANNUAL SURVEYS.

No. 996 Survey held at London Date, first Survey Aug Last Survey 25-April 1879
 on the Iron B.E. "Merle" Master Ranis
 Reg. Book. 996 Tonnage 281 Built at London When built 1863 - 11 mo
 By whom built Westwood & Owners Scutcheon & Co
 Port belonging to London Destined Voyage Dominique
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 22392 Port of Iron Classed PS. Cl. No. 1.77
 Present Condition of the Decks Good Treanails Rivets Surveyed
 Waterways --- Breasthooks and Stemson ---
 Comings --- Transoms, Pointers, and Crutches with
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings Ballast
 Lower Deck Beams & Fastenings --- Ditto ditto at other places duunap
 Planksheers --- Keelsons wood and
 Sheerstrakes --- Clamps and Shells empty
 Topsides --- Ceiling Punch and a brace
 Wales --- Rudder Good
 Plank (Bottom) and Counter --- Copper or Y.M. Cement When put on 1873
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights --- Coal Bunker, Openings, Lids, &c. --- Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom recoated. Docked. Undocked. Hailed the day on which she was surveyed. as far as could be seen she appeared in good condition and eligible in my opinion to remain as classed

Committee's Minute 6th May, 1879,
 Character assigned 100A1
T.M.W.

Will. C. Davey
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) --- Paid --- 18 ---

No. 17 Survey held at London Date, first Survey Aug Last Survey 25-April 1879
 on the Iron S. "Yarkand" Master J. Fallander
 Reg. Book. 17 Tonnage 1311 Built at Barrow When built 1877 - 1 mo
 By whom built Barrow & Co Ltd Owners E. Bates & Sons
 Port belonging to Liverpool Destined Voyage Not fixed
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 20483 Port of Iron Classed 100A1
 Present Condition of the Decks Good Treanails Rivets Good
 Waterways --- Breasthooks and Stemson ---
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---
 Planksheers --- Keelsons ---
 Sheerstrakes --- Clamps and Shells ---
 Topsides --- Ceiling ---
 Wales --- Rudder ---
 Plank (Bottom) and Counter --- Copper or Y.M. Cement When put on 1877
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights --- Coal Bunkers, Openings, Lids, &c. --- Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom painted. Some ceiling lifted cement Examined & found good. She is in good condition and eligible in my opinion to remain as classed

Committee's Minute 6th May, 1879,
 Character assigned 100A1
T.M.W.

Will. C. Davey
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) --- Paid --- 18 ---