

No. 4340 Survey held at Newcastle Date, first Survey 28th and Last Survey 30th April 1879.
No. in Reg. Book. 1254 on the Iron S.S. "Ariel" Master Jensen 23379 Apr 28
Tonnage 292 Built at Hull When built 1865-7 Mo 30
By whom built Humber Iron Works Owners H. W. Clausen
Port belonging to Nyborg Destined Voyage Baltic
If Surveyed Afloat or in Dry Dock St. Peters Dock

Last Survey, No. 21034 Port of Ivan

Classed

Years assigned.

Character in Register Book.

A1

Present Condition of the

Decks Good

Waterways do.

Comings do.

Upper Deck Beams & Fastenings do.

Lower Deck Beams & Fastenings do.

Planksheers do.

Sheerstrakes do.

Topsides do.

Wales do.

2229
Planks (Bottom) and Counter do.

Ironails Good

Breasthooks and Stemson do.

Transoms, Pointers, and Crutches do.

Timbers of the Frame at the Openings do.

Ditto ditto at other places do.

Keelsons do.

Clamps and Shelves do.

Ceiling do.

Rudder do.

Copper or Y.M. ✓ When put on ✓

Caulking of

Bottom, Deck, & Waterways Good where tried

Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good

General Observations, Opinion as to Class, &c.

This vessel's bottom has now been cleaned and recoated; the rudder lifted and the lower pintle bushed. She is in good & efficient condition, and eligible in my opinion to remain as classed.

Committee's Minute

9th May, 1879

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18