

## ANNUAL SURVEYS.

No. 26476 Survey held at Liverpool Date, first Survey 12<sup>th</sup> Feb Last Survey 20<sup>th</sup> Feb 1879  
 No. in on the S. "Stockbridge" Master G. Laing  
 Reg. Book. 1123 Tonnage 1499 Built at Stundeland When built 1869-5 m.  
1448 By whom built Oswald Owners J. Hourse  
 Port belonging to London Destined Voyage Barbadoes  
 If Surveyed Afloat or in Dry Dock Queen Q. Dock

Last Survey, No. 19990 Port of Iron

Present Condition of the

Decks	good	Treenails	Rivets	good	Classed	Years assigned.	Character in Register Book.
Waterways	"	Breasthooks and Stemson	"	"	S.S. Lon. No 2-77	12.77	*A1
Comings	"	Transoms, Pointers, and Crutches	"	"	Windlass and Capstan	Complete & good	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Pumps	"	
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Boats	"	
Planksheers	"	Keelsons	"	"	Masts, Yards, &c.	"	
Sheerstrakes	"	Clamps and Shelves	"	"	Condition, how ascertained	inspection	
Topsides	"	Ceiling	"	"	Sails	good	
Wales	"	Rudder	"	"	Anchors, No. of	"	
Plank (Bottom) and Counter	"	Copper or Y.M. Cement When put on	69.	"	Cables	"	
Engine Room Skylights	—	Caulking of	Bottom, Deck, & Waterways	good	Hawsers and Warps	"	
Coal Bunker, Openings, Lids, &c.	—	Scuppers	good	good	Standing and Running Rigging	"	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	good	good	Hatches	good	

This vessel has now been placed in graving dock, the bottom cleaned & painted, is in good condition & eligible in my opinion to remain as classed

Committee's Minute Liverpool May 13<sup>th</sup> 1879

Character assigned \*A1

Geo. T. Cooper

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey 10<sup>th</sup> March Last Survey 10<sup>th</sup> May 1879  
 No. in on the Sh. George Bewley Master J. Bewley  
 Reg. Book. 104 Tonnage 1040 Built at Harbington When built 1874-12 m.  
1064 By whom built Williamson Owners J. Bewley &  
 Port belonging to Liverpool Destined Voyage San Francisco  
 If Surveyed Afloat or in Dry Dock Queen Q. Dock

Last Survey, No. 20210 Port of Iron

Present Condition of the

Decks	good	Treenails	Rivets	good	Classed	Years assigned.	Character in Register Book.
Waterways	"	Breasthooks and Stemson	"	"	100 A1	1.78	
Comings	"	Transoms, Pointers, and Crutches	"	"	Windlass and Capstan	Complete & good	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Pumps	"	
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Boats	"	
Planksheers	"	Keelsons	"	"	Masts, Yards, &c.	"	
Sheerstrakes	"	Clamps and Shelves	"	"	Condition, how ascertained	inspection	
Topsides	"	Ceiling	"	"	Sails	good	
Wales	"	Rudder	"	"	Anchors, No. of	Complete	
Plank (Bottom) and Counter	"	Copper or Y.M. Cement When put on	77	"	Cables	"	
Engine Room Skylights	—	Caulking of	Bottom, Deck, & Waterways	good	Hawsers and Warps	"	
Coal Bunkers, Openings, Lids, &c.	—	Scuppers	good	good	Standing and Running Rigging	good	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	good	good	Hatches	good	

This vessel has now been placed in graving dock, the bottom cleaned & recoated is in good condition & eligible in my opinion to remain as classed

Committee's Minute Liverpool May 13<sup>th</sup> 1879

Character assigned 100 A1

Geo. T. Cooper

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18



Stockbridge  
George Shroley

2647b



© 2019

Lloyd's Register  
Foundation