

ANNUAL SURVEYS.

23426.38086

No. 292 Survey held at London Date, first Survey 28 April 1879 Last Survey 1 May 1879
 on the Scw Sr. Thornborough Master Coleman

Reg. Book. 463 Tonnage 739 Built at Newcastle When built 1876 8mo
629 By whom built Palmer's Co Owners J. Fenwick
 Port belonging to London Destined Voyage Coasting
☒ Surveyed Afloat or in Dry Dock On the hard outside Limekiln Dock

Last Survey, No. 21486 Port of Iron

Classed 90 A 1
 Years assigned. 7.78
 Character in Register Book

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Rivets <u>Good</u>
Waterways <u>D</u>	Breasthooks and Stemson <u>D</u>	
Comings <u>D</u>	Transoms, Pointers, and Crutches <u>D</u>	
Upper Deck Beams & Fastenings <u>D</u>	Timbers of the Frame at the Openings <u>D</u>	
Lower Deck Beams & Fastenings <u>D</u>	Ditto ditto at other places <u>D</u>	
Planksheers <u>D</u>	Keelsons <u>D</u>	
Sheerstrakes <u>D</u>	Clamps and Shelves <u>D</u>	
Topsides <u>D</u>	Ceiling <u>D</u>	
Wales <u>D</u>	Rudder <u>D</u>	
Plating <u>D</u>	Copper or V.M. Cement When put on <u>76</u>	
Plank (Bottom) and Counter <u>D</u>	Caulking of <u>Good</u>	
Engine Room Skylights <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>	
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>D</u>	
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways <u>Good</u>	Hatches <u>D</u>

She now appears to be in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 24 May 1879

Character assigned 90 A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) PAID 18

© 2019 Lloyd's Register Foundation
 180484-0334