

ANNUAL SURVEYS.

No. 23439 Survey held at London Date, first Survey May 6th Last Survey May 8th 1879
 No. in on the 8 Celestial Empire Master J Duncan
 Reg. Book. 474 Tonnage 1757 Built at Sunderland When built 1877 8M
 By whom built Osborne Owners J Duncan
 Port belonging to London Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Penton Victoria Dock

Last Survey, No. 21087 Port of Iron Classed 100A-8.77
 Years assigned. 6.78 Character in Register Book.
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on None
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Coated

She is now in good condition
Supplied and entitled to remain as classed.
Boiler Anchor 38.0.12 tested to 34.11.27 Witherton 26 April 1879 signed J & Lewis

Committee's Minute 16th May, 1879
 Character assigned 100A-8.77
TRW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 289 Survey held at London Date, first Survey April 12th Last Survey April 26th 1879
 No. in on the SS Benarty Master J Potter
 Reg. Book. 289 Tonnage 1119 Built at Glasgow When built 1876 10M
 By whom built Barclay Owners W Thomson & Co
 Port belonging to Leith Destined Voyage Japan & China
 If Surveyed Afloat or in Dry Dock Greens Is. St

Last Survey, No. 17203 Port of Iron Classed 100A-11.76
 Years assigned. 11.76 Character in Register Book.
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on None
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Coated

She is now in good condition
and entitled to remain as classed

Committee's Minute 16th May, 1879
 Character assigned 100A-11.76
TRW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18