

ANNUAL SURVEYS.

No. 477 Survey held at London Date, first Survey April 26 Last Survey May 13 1879
 No. in on the SS Glenlyon Master J. Wallace
 Reg. Book. 477 Tonnage 1373 Built at Glasgow When built 1872-1873
 By whom built Law & Glas Co Owners A & G Gow & Co
 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 21825 Port of Iron

Classed 100A/1078
 SS Lon M 77

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped & Coated

She is now in good condition and entitled to remain as classed.

Committee's Minute 20th May, 1879.

Character assigned 100A/1
TRW

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 218 Survey held at London Date, first Survey April 16 Last Survey May 9 1879
 No. in on the SS Despatch Master J. Rust
 Reg. Book. 218 Tonnage 465 Built at Newcastle When built 1863 12M
 By whom built Palmer Owners J. Fenwick & Son
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 20932 Port of Iron

Classed A/578
 SS Mace M 378

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped & Coated

She is now in good condition and entitled to remain as classed.

Committee's Minute 20th May, 1879.

Character assigned A/1
TRW

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18