

## ANNUAL SURVEYS.

23431

No. 1490 Survey held at West Hartlepool Date, first Survey 1879 Last Survey 14 May 1879  
No. in on the Sw. Jr. "Agnes" Master W. Irvine  
Reg. Book. 259 Tonnage 11042 Built at West Hartlepool When built 1877-9 mo  
By whom built Irvine Owners R. Irvine & Co.  
Port belonging to West Hartlepool Destined Voyage America  
If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 19644 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A1

Present Condition of the Decks GoodTreenails Pinets GoodBreasthooks and Stemson GoodTransoms, Pointers, and Crutches GoodTimbers of the Frame at the Openings GoodDitto ditto at other places GoodKeelsons GoodClamps and Shelves GoodCeiling GoodRudder GoodCopper or Y.M. Good When put on GoodCaulking of Bottom, Deck, & Waterways GoodWindlass and Capstan GoodPumps 4 & GoodBoats 4 & GoodMasts, Yards, &c. GoodCondition, how ascertained From DeckSails GoodAnchors, No. of 3 Bower 1 Stem 2 KedgCables GoodHawsers and Warps 11-12-7-7-6 in GoodStanding and Running Rigging Good

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c. Now done Bottom cleaned down & coated with paint & black barnish.  
Is now in a good & efficient state, fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now classed 100 A1

Committee's Minute

20th May. 1879.

S. P. Gladstone

Character assigned

100 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

T13W Certificate (if required) Paid 18

No.        Survey held at        Date, first Survey        Last Survey        18        
No. in on the        Master         
Reg. Book.        Tonnage        Built at        When built         
By whom built        Owners         
Port belonging to        Destined Voyage         
If Surveyed Afloat or in Dry Dock       

Last Survey, No.       Port of       

Classed

Years assigned.

Character in Register Book.

Present Condition of the Decks       Treenails       Breasthooks and Stemson       Transoms, Pointers, and Crutches       Timbers of the Frame at the Openings       Ditto ditto at other places       Keelsons       Clamps and Shelves       Ceiling       Rudder       Copper or Y.M.        When put on       Caulking of Bottom, Deck, & Waterways       Windlass and Capstan       Pumps       Boats       Masts, Yards, &c.       Condition, how ascertained       Sails       Anchors, No. of       Cables       Hawsers and Warps       Standing and Running Rigging       Engine Room Skylights       Coal Bunkers, Openings, Lids, &c.       Scuppers       Cargo and Main Hatchways       Hatches       General Observations, Opinion as to Class, &c.       

Committee's Minute

18


Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18



© 2019

Lloyd's Register Foundation

120N484-0432