

19/5/78

## ANNUAL SURVEYS. 23526 38/31

Paid 20.5.79

No. 67 Survey held at London Date, first Survey May 1<sup>st</sup> Last Survey May 17<sup>th</sup> 1879  
 No. in on the S Famenoth Master W. C. Auld  
 Reg. Book. 67 Tonnage 983 Built at Glasgow When built 1876 4M  
 By whom built Dobie Owners J. Cook  
 Port belonging to Aberdeen Destined Voyage Mackland  
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 2246 Port of Iron Classed 100A 5.78  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on New  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom coated

She is now in good condition and entitled to remain as classed.  
Chain cables ranged on the Quay for Government Surveyor & examined by me 270 fathoms in good condition

Committee's Minute 23rd May, 1879.  
 Character assigned 100A  
DTBW

Senhouse Martinade  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 439 Survey held at London Date, first Survey April 23 Last Survey May 6<sup>th</sup> 1879  
 No. in on the SS John McIntyre Master W. Wake  
 Reg. Book. 439 Tonnage 670 Built at Newcastle When built 1863 S.M.  
 By whom built Palmer Owners J. Fenwick & Son  
 Port belonging to London Destined Voyage not fixed when last seen  
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 20940 Port of Iron Classed CT 5.78  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on New  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom coated

She is now in good condition and entitled to remain as classed

Committee's Minute 23rd May, 1879.  
 Character assigned CT  
DTBW

Senhouse Martinade  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18