

ANNUAL SURVEYS.

23534
Rev 26/5/79

No. 4193 Survey held at West Hartlepool Date, first Survey Last Survey 21st May 1879
No. in on the S.S. "Lady Hilda" Master M. Nicholson
Reg. Book. 94 Tonnage 269 Built at Whitby When built 1876-1 mo
By whom built Jarvis Owners Whitby Steam Ship Co.
Port belonging to Whitby Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock Afloat in West Dock

Last Survey, No. 19621 Port of Iron

Classed 90 A1

Present Condition of the

Decks Good
Waterways Gutter Good
Comings Good
Upper Deck Beams & Fastenings Good
Lower Deck Beams & Fastenings "
Planksheers
Sheerstrakes Good
Topsides Good
Wales Good
Plank (Bottom) and Counter Good when seen

Treenails Good
Breasthooks and Stenson Good
Transoms, Pointers, and Crutches Good
Timbers of the Frame at the Openings Good
Ditto ditto at other places Good
Keelsons Good
Clamps and Shelves
Ceiling Good
Rudder Good
Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways Good

Windlass and Capstan Good
Pumps 4 2 Good
Boats 2 2 Good
Masts, Yards, &c. Good
Condition, how ascertained From deck
Sails Good
Anchors, No. of 3 Bowers 1 Stream 1 Budge
Cables Good
Hawsers and Warps 1 1/2 D-6 1/2-6-15 inch Good
Standing and Running Rigging Good

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Is now in a good & efficient state, fit for the safe carriage of dry & perishable goods to & from all parts of the World & may in my opinion remain as now classed 90 A1

Committee's Minute

27th May, 1879.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
Reg. Book. Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of

Classed

Present Condition of the

Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter

Treenails
Breasthooks and Stenson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18