

ANNUAL SURVEYS.

No. 4874 Survey held at Glasgow Date, first Survey 2nd May Last Survey 7th May 1879
 No. in on the 1st pr State of Virginia Master Morris
 Reg. Book. 1081 Tonnage 2473 Built at Glasgow When built 1873
 By whom built Long Glasgow & Co. Ltd Owners State Steam Ship Co. Ltd
 Port belonging to Glasgow Destined Voyage By New York
 If Surveyed Afloat or in Dry Dock Govan dry dock and afloat

Last Survey, No. 20407 Port of Glasgow Classed 100 A1
 Present Condition of the
 Decks Good Treasures None Breasthooks and Stemson Good
 Waterways " Transoms, Pointers, and Crutches "
 Comings " Timbers of the Frame at the Openings "
 Upper Deck Beams & Fastenings " Ditto ditto at other places "
 Lower Deck Beams & Fastenings " Keelsons "
 Planksheers " Clamps and Shelves "
 Sheerstrakes " Ceiling "
 Topsides " Rudder "
 Wales " Copper or V.M. Cum When put on 73
 Plank (Bottom) and Counter " Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

This vessel is now in good and efficient condition eligible to remain as classed 100 A1.

Committee's Minute 23rd May, 1879.
 Character assigned 100 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 4874 Survey held at Glasgow Date, first Survey 15th May Last Survey 15th May 1879
 No. in on the 3rd "Chilian" Master A. Bowen
 Reg. Book. 690 Tonnage 634 Built at Glasgow When built 1875-9 Mc
 By whom built J & W. Henderson & Co Owners Donaldson Bros
 Port belonging to Glasgow Destined Voyage Buenos Ayres
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 15244 Port of Glasgow Classed 100 A1
 Present Condition of the
 Decks Good Treasures None Breasthooks and Stemson Good
 Waterways " Transoms, Pointers, and Crutches "
 Comings " Timbers of the Frame at the Openings "
 Upper Deck Beams & Fastenings " Ditto ditto at other places "
 Lower Deck Beams & Fastenings " Keelsons "
 Planksheers " Clamps and Shelves "
 Sheerstrakes " Ceiling "
 Topsides " Rudder "
 Wales " Copper or V.M. Cum When put on 1875
 Plank (Bottom) and Counter Not Seen Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

This vessel is now in good condition, in my opinion eligible to remain as Classed.

Committee's Minute 23rd May, 1879.
 Character assigned 100 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18