

ANNUAL SURVEYS.

No. 4634 Survey held at Greenock Date, first Survey 1 May Last Survey 1 May 18 79
 No. in on the Iron S.S. "Bertha" Master M. Gregor
 Reg. Book. 354 Tonnage 251 Built at Glasgow When built 10th 10 mo
 By whom built Wingate Owners A. L. Seligman
 Port belonging to Glasgow Destined Voyage Dunkirk
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. Port of Glyde Classed A1
 Present Condition of the
 Decks Good where seen Rinets Good where seen 3.64 3.79
 Waterways — Breasthooks and Stemson —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wales — Rudder —
 Plank (Bottom) and Counter — Copper or Y.M. — When put on —
 Caulking of Bottom, Deck, & Waterways Good where seen
 Windlass and Capstan 2w Good
 Pumps —
 Boats —
 Masts, Yards, &c. —
 Condition, how ascertained by observation
 Sails well found
 Anchors, No. of Good
 Cables —
 Hawser and Warps —
 Standing and Running Rigging —
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Hold cleared. Rudder bands repaired. Renewing shaft &c. Bottom scraped & repainted. Ship is in good and efficient condition eligible in my opinion to remain as Classed A1

Committee's Minute 30th May, 18 79 Edwin R. Leachman
 Character assigned A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid —

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawser and Warps
 Standing and Running Rigging
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid