

10/6/79

# ANNUAL SURVEYS. 23658 38193

Recd 11.6.79

No. \_\_\_\_\_ Survey held at London Date, first Survey June 3<sup>rd</sup> Last Survey June 4<sup>th</sup> 1879  
 No. in on the S Duchep of Argyll Master J Mathias  
 Reg. Book. 463 Tonnage 1689 Built at Stockton When built 1874 7M  
 By whom built Richardson Owners M & R Wright  
 Port belonging to Liverpool Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 21126 Port of Liverpool Classed 100 A1 678  
 Years assigned. 85 Character in Register Book. See M 1-78

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Condition, how ascertained	<u>From SK</u>
Planksheers	"	Keelsons	"	"	Sails	<u>Good</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors, No. of <u>3 Bro. St &amp; Redys</u>	"
Topsides	"	Ceiling	"	"	Cables <u>Part on SK</u>	<u>Good</u>
Wales	"	Rudder	"	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>now</u>	"	"	Standing and Running Rigging	"
Engine Room Skylights	<u>✓</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	"	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>✓</u>	Scuppers	<u>Good</u>	"	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. Bottom coated.  
*She is now in good condition and entitled to remain as classed.*

Committee's Minute 13th June, 1879. Senhouse Martindale  
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TRW Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at London Date, first Survey April 21 Last Survey May 31<sup>st</sup> 1879  
 No. in on the S Zealandia Master J Sellar  
 Reg. Book. 74 Tonnage 1116 Built at Glasgow When built 1869 6M  
 By whom built Comie Owners Shaw Savill & Co  
 Port belonging to Southampton Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 21035 Port of Liverpool Classed \*A1 5.78  
 Years assigned. 85 Character in Register Book. See M 2-77

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Condition, how ascertained	<u>From Deck</u>
Planksheers	"	Keelsons	"	"	Sails	<u>Good</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors, No. of <u>3 Bro. St &amp; Redys</u>	"
Topsides	"	Ceiling	"	"	Cables <u>Part on Deck</u>	<u>Good</u>
Wales	"	Rudder	"	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>now</u>	"	"	Standing and Running Rigging	"
Engine Room Skylights	<u>✓</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	"	Cargo and Main Hatchways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>✓</u>	Scuppers	<u>Good</u>	"	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. Bottom coated.  
*She is now in good condition and entitled to remain as classed.*

Committee's Minute 13th June, 1879. Senhouse Martindale  
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TRW Paid \_\_\_\_\_ 18 \_\_\_\_\_

