

ANNUAL SURVEYS.

23686

No. 2764 Survey held at Swansea Date, first Survey And Last Survey 31st May 1879
 No. in on the S.S. "Plantagenet" Master Campbell
 Reg. Book. 461 Tonnage 5357 Built at London When built 1869 - 3rd Mo
 By whom built Samuda Owners J. Bacon
 Port belonging to London Destined Voyage Barcelona
 If Surveyed Afloat or in Dry Dock Albion dry dock

Last Survey, No. 20446 Port of Iron.

Classed

Years assigned. Character in Register Book.

A 1

S.S. No 3-78
3-78

Present Condition of the

Decks

good

Treenails Rivets

good

Waterways

Breasthooks and Stemson

Comings

Transoms, Pointers, and Crutches

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Lower Deck Beams & Fastenings

Ditto ditto at other places

Planksheers

Keelsons

Sheerstrakes

Clamps and Shells

Topsides

Ceiling

Wales

Rudder

Plank (Bottom) and Counter

Copper or V.M. Paint When put on Now

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained From deck

Sails Surt

Anchors, No. of complete

Cables Not ranged

Hawsers and Warps Sufficient

Standing and Running Rigging

Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers

Cargo and Main Hatchways good Hatches

General Observations, Opinion as to Class, &c.

This Vessel has been surveyed by me in dry dock, has now been cleaned and painted on the outside, is in good condition and in my opinion eligible to remain as classed.

Committee's Minute

13th June,

1879.

Thos Ashton

Character assigned

A 1

TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 21/- Paid 10 June 1879

No. 2764 Survey held at Swansea Date, first Survey And Last Survey 5th June 1879
 No. in on the Iron Barge "Maxima" Master Bowen
 Reg. Book. 856 Tonnage 474 Built at Newcastle When built 1867 - 9th Mo
 By whom built Palmer Owners G B Meager
 Port belonging to Swansea Destined Voyage Montevideo
 If Surveyed Afloat or in Dry Dock Villiers dry dock

Last Survey, No. 20568 Port of Iron

Classed

Years assigned. Character in Register Book.

A 1

S.S. No 3-77
3-78

Present Condition of the

Decks

good

Treenails Rivets

good

Waterways

Breasthooks and Stemson

Comings

Transoms, Pointers, and Crutches

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Lower Deck Beams & Fastenings

Ditto ditto at other places

Planksheers

Keelsons

Sheerstrakes

Clamps and Shells

Topsides

Ceiling

Wales

Rudder

Plank (Bottom) and Counter

Copper or V.M. Paint When put on Now

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained From deck

Sails Two Suits

Anchors, No. of 3 B, 2 H

Cables Not ranged

Hawsers and Warps Sufficient

Standing and Running Rigging

Engine Room Skylights Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways good Hatches

General Observations, Opinion as to Class, &c.

This Vessel has now been cleaned and painted is in good condition and in my opinion eligible to remain as classed.

Committee's Minute

10th June,

1879.

Thos Ashton

Character assigned

A 1

TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) No Fee received

No 2764 Swansea



© 2019

Lloyd's Register
Foundation