

# ANNUAL SURVEYS.

No. 4584 Survey held at Cardiff Date, first Survey 17th June Last Survey 1879  
 No. in on the 1 Reg. Book. 581 Tonnage 65 898 Built at Newcastle Master Boase  
 By whom built Schlesinger Owners C. E. Hallybrass & Co  
 Port belonging to Cardiff Destined Voyage Malta  
 If Surveyed Afloat or in Dry Dock in Dry Dock

Last Survey, No. 23034 Port of London Classed 100.A.1  
 Present Condition of the Decks Good Treenails Prots where seen Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons Not seen  
 Sheerstrakes " Clamps and Shelves Strainers &c  
 Topsides Plating Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on hon  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.  
Placed on Gridiron. Bottom cleaned & coated. So far as seen the vessel appears in good & efficient condition, eligible to retain her Character 100.A.1  
See Engineer Surveyor's Report. W & Co forwarded herewith.  
See Rec (Machinery) £2.2.0

Committee's Minute 17th June, 1879. Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Character assigned 100.A.1 Certificate (if required) 12/6 Paid 1879  
MC T.B.W.

No.        Survey held at        Date, first Survey        Last Survey 18  
 No. in on the        Master         
 Reg. Book.        Tonnage        Built at        When built         
 By whom built        Owners         
 Port belonging to        Destined Voyage         
 If Surveyed Afloat or in Dry Dock       

Last Survey, No.        Port of        Classed         
 Present Condition of the Decks        Treenails         
 Waterways        Breasthooks and Stemson         
 Comings        Transoms, Pointers, and Crutches         
 Upper Deck Beams & Fastenings        Timbers of the Frame at the Openings         
 Lower Deck Beams & Fastenings        Ditto ditto at other places         
 Planksheers        Keelsons         
 Sheerstrakes        Clamps and Shelves         
 Topsides        Ceiling         
 Wales        Rudder         
 Plank (Bottom) and Counter        Copper or Y.M.        When put on         
 Caulking of Bottom, Deck, & Waterways         
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.  
        
        
        
 Committee's Minute 18  
 Character assigned        Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)        Paid



*Slane d'arnt*



© 2019

Lloyd's Register  
Foundation