

ANNUAL SURVEYS. 23819

No. 4900 Survey held at Glasgow Date, first Survey 9th June Last Survey 11th June 1879
 No. in on the Barge "Sichir" Master J. Black
 Reg. Book. 621 Tonnage 1153 Built at Glasgow When built 1876-68
 By whom built Stephen Owners J. Smith
 Port belonging to Glasgow Destined Voyage Regaputarn
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 20638 Port of Iron Classed 100A Years assigned. 3.78 Character in Register Book.
 Present Condition of the
 Decks Good Timbers Planks Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches Not Seen
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings " Ditto Ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling When seen good, a large quantity of outward cargo on board
 Wales " Rudder Good
 Plate " Copper or F.A. Cement When put on 1876
 Plank (Bottom) and Counter " Caulking of "
 Bottom, Deck, & Waterways Good
 Engine Room Stagnant Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Excellent rail & bulwark on Starboard side repaired part renewed. Bottom cleaned and painted. Mizen yards sent down. Vessel now Barge rigged. She is now in good condition in my opinion eligible to remain as classed.

Committee's Minute 20th June, 1870.
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 4900 Survey held at Glasgow Date, first Survey 9th June Last Survey 11th June 1879
 No. in on the Ship "Loch Vennachar" Master J. S. Cramie
 Reg. Book. 625 Tonnage 1485 Built at Glasgow When built 1875-8
 By whom built Thomson Owners Glasgow Shipping Co
 Port belonging to Glasgow Destined Voyage Dunblane
 If Surveyed Afloat or in Dry Dock J. & R. Henderson's Dry Dock

Last Survey, No. 21205 Port of Iron Classed 100A Years assigned. 6.78 Character in Register Book.
 Present Condition of the
 Decks Good Timbers Planks Good
 Waterways " Breasthooks and Stemson Not Seen
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings " Ditto Ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling Good when seen. 350 tons of stone ballast on board
 Wales " Rudder Good
 Plate " Copper or F.A. Cement When put on 1875
 Plank (Bottom) and Counter " Caulking of "
 Bottom, Deck, & Waterways Good
 Engine Room Stagnant Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. Vessel to be submitted to S.S.W. 1 on her return. The bottom cleaned and coated with Mr. Innes' Composition. She is now in good condition in my opinion eligible to remain as classed.

Committee's Minute 20th June, 1870.
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

