

ANNUAL SURVEYS.

23822

No. 26529 Survey held at Liverpool Date, first Survey May 26th Last Survey May 27th 1879
 No. in on the Ship "Sorata" Master Pasley
 Reg. Book. 850 Tonnage 786 Built at Liverpool When built 1869-4 mo.
 By whom built Bowdler Owners J. B. Hainsley
 Port belonging to Liverpool Destined Voyage Lima
 If Surveyed Afloat or in Dry Dock Canning Dry Dock

Last Survey, No. 20640 Port of Iron Classed S.S. Liv No 2-78. Years assigned. 4-78. Character in Register Book. *A
 Present Condition of the Decks Good Treenails Rivets. Good
 Waterways ✓ Breasthooks and Stimson ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓
 Planksheers ✓ Keelsons ✓
 Sheerstrakes ✓ Clamps and Shells ✓
 Topsides ✓ Ceiling ✓
 Wales ✓ Rudder ✓
 Plank (Bottom) and Counter ✓ Copper or Y.M. Cement When put on 69
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool June 20th 1879 Character assigned *A
 Surveyor to Lloyd's Register of British and Foreign Shipping. T. Skilston
 Certificate (if required) ✓ Paid 18

No. ✓ Survey held at Liverpool Date, first Survey May 14th Last Survey May 15th 1879
 No. in on the Ship "Cape Breton" Master G. Young
 Reg. Book. 194 Tonnage 1421 Built at Glasgow When built 1877-12 mo.
 By whom built Thomson Owners A. Lyle & Sons.
 Port belonging to Greenock Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock

Last Survey, No. 19923 Port of Iron Classed 100 AL. Years assigned. 1-78. Character in Register Book. *A
 Present Condition of the Decks Good Treenails Rivets. Good
 Waterways ✓ Breasthooks and Stimson ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓
 Planksheers ✓ Keelsons ✓
 Sheerstrakes ✓ Clamps and Shells ✓
 Topsides ✓ Ceiling ✓
 Wales ✓ Rudder ✓
 Plank (Bottom) and Counter ✓ Copper or Y.M. Cement When put on 77
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted cleaned and coated with paint and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool June 20th 1879. Character assigned 100 A
 Surveyor to Lloyd's Register of British and Foreign Shipping. T. Skilston
 Certificate (if required) ✓ Paid 18

Sorata

Cape Melton

26029.



© 2019

Lloyd's Register
Foundation