

23849  
REPORT of SURVEY for REPAIRS, &c. 38245

No. 147  
No. in Reg. Book 147  
Survey held at London  
Date, first Survey April 1879  
Last Survey June 20th 1879  
Master Davies  
Official Number 1058  
Tonnage under Tonnage Deck 986  
Ditto of Spar Deck, or Arming Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage 1058  
Crew Space, as per Rule 1058  
Register Tonnage, cut on Beam 1058  
Engine Room  
Reg. Tons as St'mer, cut on Bm.

Built at Glasgow  
When built 1865 3  
Owners Shaw Savill & Co.  
Port belonging to Southampton  
Residence  
By whom built Connell  
Destined Voyage  
If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock  
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.  
Classed A 1.5.78  
Last Survey, No. 20898 Port Iron  
Character in Register Book 55 ton m 3.75.

REPAIRS, OR EXAMINATION AS PER RULE

At the present time done by the owners  
the Main Deck renewed with well seasoned  
Yellow Pine fastened with Screw Bolts & Nuts.  
Bottom boarded Deck banded.

Present Condition of the Decks	New	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Waterways	"	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	"	Ditto Ditto at other places	"	"	Condition, how ascertained	From St.
Planksheers	"	"	Keelsons	"	"	Sails	Good
Sheerstrakes	"	"	Clamps and Shelves	"	"	Anchors No. of 3 Br. St. & Kedges	"
Topsides	"	"	Ceiling	"	"	Cables Part on St.	Good
Wales	"	"	Rudder	"	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	"	Copper	Scuted	When put on	Standing & Running Rigging	"
Engine Room Skylights	"	"	Caulking of	"	"	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	"	"	Bottom, Deck, & Waterways	"	Good	Hatches	Good
Scuppers	"	"					

General Observations, Opinion as to Class, &c.

She is now in good condition and  
entitled to remain as classed. The owners intend  
to put her through SS M1 on her return Voyage

The Amount of Entry Fee ... £ 3 : : : received by me, C. H. R.  
Special ... £ 2 : 2 : 28 June 1879  
Certificate (if required) ... £ : 5 :  
(Travelling Expenses, if any, £ )  
Committee's Minute 24th June, 1879  
Character assigned  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
L. R. © 2019 Lloyd's Register Foundation  
IRON 485-0371