

## ANNUAL SURVEYS. 23874

No. 26551 Survey held at Liverpool Date, first Survey May 20 Last Survey June 10 1878  
 No. in on the Iron 135 "Ladstock" Master Williams  
 Reg. Book. 41 Tonnage 216 Built at Whitehaven When built 1876-9 mo  
 By whom built Whitehaven S.C. Owners H. Cornell & Co  
 Port belonging to Liverpool Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Afloat & in the River & in dry dock

Last Survey, No. 14139 Port of Liverpool Classed 100 A-1-9-78  
 Present Condition of the Decks Good Treennails Reels - Good  
 Waterways " Breasthooks and Stems "  
 Comings " Transoms, Painters, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Rudder "  
 Copper or Y.M. Cen When put on 76  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

The bottom scraped and painted. This vessel is now in good condition and in my opinion eligible to remain as Classed.

Committee's Minute Liverpool July 4<sup>th</sup> 1876  
 Character assigned 100 A-1.

E. B. Wheeler  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey June 5 Last Survey June 10 1879  
 No. in on the Iron 1<sup>st</sup> "Hugh Brown" Master Haynes  
 Reg. Book. 500 Tonnage 176 Built at Harrington When built 1871-8 mo  
 By whom built Williamson Owners W. Price  
 Port belonging to Whitehaven Destined Voyage Maracibo  
 If Surveyed Afloat or in Dry Dock Afloat & in the River & in dry dock

Last Survey, No. 22574 Port of Liverpool Classed 100 A-1-1-79  
 Present Condition of the Decks Good Treennails Reels - Good  
 Waterways " Breasthooks and Stems "  
 Comings " Transoms, Painters, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Rudder "  
 Copper or Y.M. Cen When put on 71  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

The bottom scraped & painted. This vessel is now in good condition and in my opinion eligible to remain as Classed.

Committee's Minute Liverpool July 2<sup>nd</sup> 1879.  
 Character assigned 100 A-1

E. B. Wheeler  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18



Hadstock  
Hugh Ewing  
26551



© 2019

Lloyd's Register  
Foundation