

ANNUAL SURVEYS. 2394

No. 1449 Survey held at Newcastle Date, first Survey 16th and Last Survey 20th June 1877
 No. in on the Iron Scw. Sr. "Tagus." Master M. Manson
 Reg. Book. 953 Tonnage 1250 Built at Newcastle When built 1872-9 mo.
 By whom built Cole Owners H. Bucknall & S.
 Port belonging to Newcastle Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock On Wallsend Slipway

Last Survey, No. 23006 Port of Iron

Present Condition of the				Classed	Years assigned.	Character in Register Book
Decks	<u>good</u>	<u>Ironails</u>	<u>rivets</u>	<u>good</u>	<u>100 A.1</u>	<u>3.79</u>
Waterways	<u>g^o</u>	Breasthooks and Stemson		<u>g^o</u>		
Comings	<u>g^o</u>	Transoms, Pointers , and Crutches		<u>g^o</u>		
Upper Deck Beams & Fastenings	<u>g^o</u>	Timbers of the Frame at the Openings		<u>g^o</u>		
Lower Deck Beams & Fastenings	<u>g^o</u>	Ditto ditto at other places	<u>not seen</u>			
Planksheers	<u>g^o</u>	Keelsons		<u>good</u>		
Sheerstrakes	<u>g^o</u>	Clamps and Shelves		<u>g^o</u>		
Topsides	<u>g^o</u>	Ceiling		<u>g^o</u>		
Wales	<u>g^o</u>	Rudder		<u>g^o</u>		
Plating	<u>g^o</u>	Copper or Y.M.		<u>When put on</u>		
Plank (Bottom) and Counter	<u>g^o</u>	Caulking of				
Engine Room Skylights	<u>good</u>	Bottom, Deck, & Waterways		<u>good</u>		
Coal Bunker, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>			
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>good</u>			
		Hatches	<u>good</u>			

The bottom has been painted. This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 1st July, 18 79.

Character assigned 100 A.1

J. H. Truscott
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 1449 Survey held at Newcastle Date, first Survey 23rd and Last Survey 24th June 1877
 No. in on the Iron Scw. Sr. "Elsie." Master A. Ross
 Reg. Book. 563 Tonnage 1183 Built at Sunderland When built 1877-4 mo.
 By whom built Thompson Owners F. Gordon & Stamp
 Port belonging to Sunderland Destined Voyage Hamburg
 If Surveyed Afloat or in Dry Dock On Clelands' Slipway

Last Survey, No. 20949 Port of Iron

Present Condition of the				Classed	Years assigned.	Character in Register Book
Decks	<u>good</u>	<u>Ironails</u>	<u>rivets</u>	<u>good</u>	<u>90 A.1</u>	<u>5.78</u>
Waterways	<u>g^o</u>	Breasthooks and Stemson		<u>g^o</u>		
Comings	<u>g^o</u>	Transoms, Pointers , and Crutches		<u>g^o</u>		
Upper Deck Beams & Fastenings	<u>g^o</u>	Timbers of the Frame at the Openings		<u>g^o</u>		
Lower Deck Beams & Fastenings	<u>g^o</u>	Ditto ditto at other places	<u>not seen</u>			
Planksheers	<u>g^o</u>	Keelsons		<u>good</u>		
Sheerstrakes	<u>g^o</u>	Clamps and Shelves		<u>g^o</u>		
Topsides	<u>g^o</u>	Ceiling		<u>g^o</u>		
Wales	<u>g^o</u>	Rudder		<u>g^o</u>		
Plating	<u>g^o</u>	Copper or Y.M.		<u>When put on</u>		
Plank (Bottom) and Counter	<u>g^o</u>	Caulking of				
Engine Room Skylights	<u>good</u>	Bottom, Deck, & Waterways		<u>good</u>		
Coal Bunkers, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>			
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>good</u>			
		Hatches	<u>good</u>			

The bottom has been painted. This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 1st July, 18 79.

Character assigned 90 A.1

J. H. Truscott
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18