

# ANNUAL SURVEYS. 23939

No. 38286 Survey held at London Date, first Survey 20<sup>th</sup> July Last Survey 2<sup>nd</sup> July 1877  
 No. in on the S. S. "Agnes & Louisa" Master J. Hodgkinson  
 Reg. Book. 287 Tonnage 436 Built at Hartlepool When built 1871-19 mo  
 By whom built Withy Owners S. Clarke & Co.  
 Port belonging to London Destined Voyage Coasting  
 If Sun afloat or in Dry Dock Union by lock & afloat

Last Survey, No. 21604 Port of Trou

Present Condition of the

Decks Good

Waterways — " —

Comings — " —

Upper Deck Beams & Fastenings — " —

Lower Deck Beams & Fastenings — " —

Planksheers — " —

Sheerstrakes — " —

Topsides — " —

Wales Plate

Planks (Bottom) and under — " —

Tree-nails Keels Good

Breasthooks and Stems — " —

Transoms, Pointers, and Crutches — " —

Timbers of the Frame at the Openings — " —

Ditto ditto at other places — " —

Keelsons — " —

Clamps and Shelves — " —

Ceiling — " —

Rudder — " —

Copper or V.M. Cement When put on 71

Caulking of Bottom, Deck, & Waterways Good

Classed

Years assigned.

Character in Register Book.

90 A.1.

9-78.

S. S. Lon. No. 1-75.

Windlass and Capstan Good

Pumps — " —

Boats — " —

Masts, Yards, &c. — " —

Condition, how ascertained From beef

Sails Good

Anchor, No. of 3 1/2 18 in 2 1/2 dgs

Cables Good

Hawsers and Warps Good

Standing and Running Rigging Good

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. Bottom examined, cleaned and coated

with Paint & Tallow timbers lifted at bilges Cement in  
good condition, she is now in good and efficient condition  
and in my opinion eligible to remain as Classed.

With reference to special survey see  
Owners letter attached

Committee's Minute 22nd July, 1873.

Character assigned 90 A.1  
By Lloyd Mc 779 (see Note)

Thos Wm Blayell  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid 18

1200-924201