

10. 7. 79 - ANNUAL SURVEYS. 23942 38.264

No. 1520 Survey held at London Date, first Survey 30th June Last Survey 10th July 1879.
No. in on the Bk. "Avona" Master C. H. Martin
Reg. Book. 1520 Tonnage 696. 716. 669 Built at Stockton When built 1869 10th mo.
By whom built Richardson Owners Whitwill & Sn.
Port belonging to Bristol Destined Voyage Montreal
If Surveyed ~~Afloat~~ or in Dry Dock West India Dry Dock.

Last Survey, No. 21060 Port of Iron Classed 7.78 Character in Register Book. *A1
Present Condition of the
Decks Good Treenails Rivets Good
Waterways do Breasthooks and Stems do Windlass and Capstan Good
Comings do Transoms, Pointers, and Crutches do Pumps do
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats 3 in number do
Lower Deck Beams & Fastenings do Ditto ditto at other places not seen Masts, Yards, &c. do
Planksheers do Keelsons do Condition, how ascertained from deck & enquiry
Sheerstrakes do Clamps and Shells do Sails well found do
Topsides do Ceiling do Anchors, No. of 3 B. 1 St. 2 K do
Wales do Rudder Pintles bushed do Cables part seen do
Plating (Bottom) and Counter do Copper or F.M. Paint When put on now Hawser and Warps do
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers do Standing and Running Rigging do
General Observations, Opinion as to Class, &c. good Cargo and Main Hatchways good Hatches do

Bottom cleaned & repainted. - Rudder pintles bushed. -
Surveyed with ballast in hold under main hatch. -

This vessel is now in good condition & eligible in my opinion to remain as classed.

Committee's Minute 15th July 1879 W. Paulsen.
Character assigned A1 TBW Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. 721 Survey held at London Date, first Survey 5th July Last Survey 5th July 1879.
No. in on the S. S. "Mary Louisa" Master A. Mace
Reg. Book. 721 Tonnage 1287. 1976. 1858 Built at Newcastle When built 1878 5th mo.
By whom built Mitchell Owners Elliott, Lowrey & Dunford
Port belonging to Newcastle Destined Voyage Boston
If Surveyed ~~Afloat~~ or in Dry Dock Millwall Graving Dock

Last Survey, No. 21421 Port of Iron Classed 100 A1 Character in Register Book. 6.78
Present Condition of the
Decks Good Treenails Rivets Good
Waterways do Breasthooks and Stems do Windlass and Capstan Good
Comings do Transoms, Pointers, and Crutches do Pumps do
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats 4 in number do
Lower Deck Beams & Fastenings do Ditto ditto at other places not seen Masts, Yards, &c. do
Planksheers do Keelsons do Condition, how ascertained from deck & enquiry
Sheerstrakes do Clamps and Shells do Sails well found do
Topsides do Ceiling do Anchors, No. of 3 B. 1 St. 2 K do
Wales do Rudder do Cables part seen do
Plating (Bottom) and Counter do Copper or F.M. Paint When put on now Hawser and Warps do
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers do Standing and Running Rigging do
General Observations, Opinion as to Class, &c. good Cargo and Main Hatchways good Hatches do

Bottom cleaned & repainted. - Several rivets in rudder plating renewed. -
Surveyed with cattle fittings on board. -

This vessel is now in good condition & eligible in my opinion to remain as classed.

Committee's Minute 15th July 1879 W. Paulsen.
Character assigned 100 A1 TBW Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

