

ANNUAL SURVEYS. 23990

No. 20855 Survey held at Shull Date, first Survey 20 May Last Survey 8 July 1879
 No. in on the "Iron Steamer Neptuno" Master Lewis
 Reg. Book. 1557 Tonnage 1557 Built at N. Hytton When built 1843 - 5 mo
 By whom built Robson Owners Salisbury & Co.
 Port belonging to Liverpool Destined Voyage London
 If Surveyed Afloat or in Dry Dock Afloat and on Slipway

Last Survey, No. 20855 Port of Liverpool Classed 100. A. 1.
 Present Condition of the Decks Good When seen Good
 Waterways do Breasthooks and Stemson do Windlass and Capstan Good
 Comings do Transoms, Pointers, and Crutches do Pumps do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats 4 on board Good
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Masts, Yards, &c. Good
 Planksheers do Keelsons do Condition, how ascertained In dock &c
 Sheerstrakes do Clamps and Shelves do Sails do
 Topsides do Ceiling do Anchors, No. of 2 complete
 Wales do Rudder do Cables do
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do Hawseers and Warps do
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Placed on blocks on Slipway and the bottom cleaned and painted. Is in good condition and eligible in my opinion to remain as classed.

Committee's Minute 22nd July 1879
 Character assigned 100. A. 1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1879

No. 20484 Survey held at Shull Date, first Survey 7 July 1879
 No. in on the "Iron Steamer Marion de Ambro" Master Lewis
 Reg. Book. 94 Tonnage 1557 Built at London When built 1861. 1 mo
 By whom built Lynch Owners W. Sully & Co
 Port belonging to Shull Destined Voyage Marseilles
 If Surveyed Afloat or in Dry Dock Afloat - with pair Caps on board

Last Survey, No. 20484 Port of Liverpool Classed 90. A. 1.
 Present Condition of the Decks Good When seen Good
 Waterways do Breasthooks and Stemson do Windlass and Capstan Good
 Comings do Transoms, Pointers, and Crutches do Pumps do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Masts, Yards, &c. Good
 Planksheers do Keelsons do Condition, how ascertained In dock &c
 Sheerstrakes do Clamps and Shelves do Sails do
 Topsides do Ceiling do Anchors, No. of do
 Wales do Rudder do Cables do
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do Hawseers and Warps do
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Surveyed while afloat with pair of Caps. In board in after hold. She appears to be in good condition and eligible in my opinion to remain as classed.

Committee's Minute 22nd July 1879
 Character assigned 90. A. 1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1879