

# ANNUAL SURVEYS. 23993

No. 38282 Survey held at London Date, first Survey 11<sup>th</sup> July Last Survey 12<sup>th</sup> July 1879.  
 No. in Reg. Book. 146 on the Ship "Opawa" Master J. Friston  
 Tonnage 107.131.980 Built at Glasgow When built 1876 11<sup>th</sup> mo.  
 By whom built Stephen Owners New Zealand Shipp. Com. (lim)  
 Port belonging to London Destined Voyage Wellington  
 If Surveyed Afloat or in Dry Dock Canal Dry Dock  
 Last Survey, No. 21235 Port of Iron

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	
Waterways	<u>do</u>	Breasthooks and Stems		<u>do</u>	Windlass and Capstan
Comings	<u>do</u>	Transoms, Pointers, and Crutches		<u>do</u>	Pumps
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings		<u>do</u>	Boats <u>6 in number</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>not seen</u>		Masts, Yards, &c.
Planksheers	<u>do</u>	Keelsons		<u>do</u>	Condition, how ascertained
Sheerstrakes	<u>do</u>	Clamps and Shetfs		<u>do</u>	Sails <u>well found</u>
Topsides	<u>do</u>	Ceiling		<u>do</u>	Anchors, No. of <u>3 B. 1st. 2 R</u>
Wales	<u>do</u>	Rudder	<u>Pintles bushed</u>	<u>do</u>	Cables <u>part seen</u>
Planks (Bottom) and Counter	<u>do</u>	Copper or F.M. Paint	When put on <u>now</u>		Hawsers and Warps
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>good</u>		Standing and Running Rigging
Coal Bunker, Openings, Lids, &c.		Scuppers	<u>do</u>		Cargo and Main Hatchways
General Observations, Opinion as to Class, &c.					Hatches

Rudder pintles bushed. - Bottom cleaned & repainted. -  
Surveyed with ballast in hold all fore & aft. -

This vessel is in good condition & eligible in my opinion to remain as classed. -

Committee's Minute 22nd July, 1879  
 Character assigned 100 A 1  
TKW

W. Paulsen  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 82 Survey held at London Date, first Survey 10<sup>th</sup> July Last Survey 15<sup>th</sup> July 1879.  
 No. in Reg. Book. 82 on the Ship "Saint Margaret" Master R. Logie  
 Tonnage 1368.1428.1292 Built at Liverpool When built 1877 8<sup>th</sup> mo.  
 By whom built Royden Owners Rankin, Gilmour & Co.  
 Port belonging to Glasgow Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Cubitt Town Dry Dock  
 Last Survey, No. 19322 Port of Iron

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	
Waterways	<u>do</u>	Breasthooks and Stems		<u>do</u>	Windlass and Capstan
Comings	<u>do</u>	Transoms, Pointers, and Crutches		<u>do</u>	Pumps
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings		<u>do</u>	Boats <u>4 in number</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>not seen</u>		Masts, Yards, &c.
Planksheers	<u>do</u>	Keelsons		<u>do</u>	Condition, how ascertained
Sheerstrakes	<u>do</u>	Clamps and Shetfs		<u>do</u>	Sails <u>well found</u>
Topsides	<u>do</u>	Ceiling		<u>do</u>	Anchors, No. of <u>3 B. 1st. 2 R</u>
Wales	<u>do</u>	Rudder		<u>do</u>	Cables <u>part seen</u>
Planks (Bottom) and Counter	<u>do</u>	Copper or F.M. Paint	When put on <u>now</u>		Hawsers and Warps
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>good</u>		Standing and Running Rigging
Coal Bunker, Openings, Lids, &c.		Scuppers	<u>do</u>		Cargo and Main Hatchways
General Observations, Opinion as to Class, &c.					Hatches

Bottom cleaned & repainted. -  
Surveyed with part outward cargo under main hatch. -

This vessel is in good condition & eligible in my opinion to remain as classed. -

Committee's Minute 22nd July, 1879  
 Character assigned 100 A 1  
TKW

W. Paulsen  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18