

23997
ANNUAL SURVEYS.

No. 26572 Survey held at Liverpool Date June 21st 18 79
 on the San H. Pedro late San Antonio Master De Garro
 Tonnage 765 Built at Fumbarton When built 1872-12 mo
 By whom built McMillan Owners J Serra y Font
 Port belonging to Bilbao Destined Voyage Cuba
 If Surveyed Afloat or in Dry Dock Afloat in Camering dry dock

Last Survey, No. 18807 Port of Iron Classed 100 A1 - 5-77
 The present Condition of the
 Decks Caulked Good Timber Good Windlass and Capstan Good & efficient
 Waterways " Breasthooks and Stem " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Keelsons " Sails "
 Planksheers " Clamps and Shelves " Anchors No. of "
 Sheerstrakes " Ceiling " Cables "
 Topsides " Rudder " Hawser and Warps "
 Wals " Cem When put on 72 1/2 77 Standing & Running Rigging "
 Plank (Bottom) and Counter "
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

The bottom scraped and painted - This vessel is now in good condition and in my opinion eligible to remain as Classed -
 Committee's Minute Liverpool July 22-18 79.
 Character assigned 100 A1.
 Certificate (if required)

No. 366 Survey held at Birkenhead Date June 23rd 18 79
 on the Im J "Oxford" Master Petersen
 Tonnage 1202 Built at Tunderland When built 1869 - 9 mo
 By whom built Oswald Owners Temperley, Carter & Parker
 Port belonging to London Destined Voyage "
 If Surveyed Afloat or in Dry Dock In Great Floor dry dock

Last Survey, No. 20598 Port of Iron Classed * A1 - 5-78
 The present Condition of the
 Decks Good Timber Good Windlass and Capstan Good & efficient
 Waterways " Breasthooks and Stem " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Keelsons " Sails "
 Planksheers " Clamps and Shelves " Anchors No. of "
 Sheerstrakes " Ceiling " Cables "
 Topsides " Rudder " Hawser and Warps "
 Wals " Cem When put on 69 Standing & Running Rigging "
 Plank (Bottom) and Counter "
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

The bottom scraped and painted. This vessel is now in good condition and in my opinion eligible to remain as Classed -
 Committee's Minute Liverpool July 22-18 79.
 Character assigned * A1.
 Certificate (if required)

Pedro^{ss}

Oxford

26542.



© 2019

Lloyd's Register
Foundation