

24036. 38297.
REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. 42 on the S. Carrloch Master D. Phillip
Survey held at London Date, first Survey 7 June 79 Last Survey 17 July 1879
TONNAGE under Tonnage Deck 1194
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 1332
Crew Space, as per Rule
Register Tonnage, cut on Beam 1264
Engine Room
Reg. Tons as St mer, cut on Bm.

Built at Glasgow When built 1874 12
Owners J. S. Hunter Port belonging to Greenock
Residence
By whom built Duncan Destined Voyage Adelaide
If Surveyed Afloat or in Dry Dock Princes Dry Dock
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book. 100 1 1.78
Last Survey, No. 20185 Port Mon Classed

REPAIRS, OR EXAMINATION AS PER RULE

for S. S. No 1

Vessel placed in dry dock and her bottom scraped and painted. The timbers and on additional strakes of close ceiling lifted on both sides of the vessel right fore and aft. The cement found to be everywhere in good condition and closely adhering to the iron. Fore peak examined and found to be in good condition. Spars examined aloft.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Greenails Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Cement When put on

Caulking of

Bottom, Deck, & Waterways

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of 3 B. 15 2 K

Cables Part seen

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

The Amount of Entry Fee ... £ 4 : 4 : received by me, J. Shear

Special ... £ 4 : 4 : 20 July 1879

Certificate (if required) ... £ : : 20 July 1879

(Travelling Expenses, if any, £)

Committee's Minute 25th July, 1879

Character assigned 100A

S.S. No 1 79

IRON 436-0212

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation