

# ANNUAL SURVEYS.

38301

No.            Survey held at London Date, first Survey July 22 Last Survey July 28 1879  
 No. in on the Star of Scotia Master Hughes  
 Reg. Book. 1052 Tonnage 999 Built at Belfast When built 1864 - 11M  
 By whom built Howland Owners J. Barry & Co.  
 Port belonging to Belfast Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 2180 Port of London Classed SS 100A 3-77  
 Present Condition of the Decks good Treenails Rivets good  
 Waterways " Breasthooks and Stenson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights            Coal Bunker, Openings, Lids, &c.            Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom coated

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 25th July, 1879. Senhouse Martindale  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)            Paid            18          

No.            Survey held at London Date, first Survey June 19 Last Survey June 19 1879  
 No. in on the SS Fenellos Master Harris  
 Reg. Book. 135 Tonnage 553 Built at Glasgow When built 1873 - 11M  
 By whom built Sen & Glas & Co. Owners Globe & Ship Co.  
 Port belonging to London Destined Voyage Cronstadt  
 If Surveyed Afloat or in Dry Dock Portoon Victoria & Co.

Last Survey, No. 22967 Port of London Classed SS 100A 3-77  
 Present Condition of the Decks good Treenails Rivets good  
 Waterways " Breasthooks and Stenson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom coated

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 25th July, 1879. Senhouse Martindale  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)            Paid            18          

120M136-0291