

ANNUAL SURVEYS

No. 26581 Survey held at Liverpool Date, first Survey June 10 Last Survey June 12 18 79
 No. in on the Iron B.E. "Galatea" Master Black
 Reg. Book. 43 Tonnage 581 Built at Gundee When built 1865-6
 By whom built Brown Owners W O Taylor & Co
 Port belonging to Gundee Destined Voyage Norfolk
 If Surveyed Afloat or in Dry Dock In Canning dry dock

Last Survey, No. 2153 Port of Iron Classed *A-1-6-70
ST Pol- N-2-70

Present Condition of the
Decks

Good

Points Good

Waterways

"

Breasthooks and Stems " "

Comings

"

Transoms, Pointers, and Crutches " "

Upper Deck Beams & Fastenings

"

Timbers of the Frame at the Openings " "

Lower Deck Beams & Fastenings

"

Ditto ditto at other places " "

Planksheers

"

Keelsons " "

Sheerstrakes

"

Clamps and Shelves " "

Topsides

"

Ceiling " "

Wales

"

Rudder " "

Plank (Bottom) and Counter

"

Copper on Y.M. Cen When put on 69

Caulking of

Bottom, Deck, & Waterways Good

Engine Room Skylights Coal Bunker, Openings, Lids, &c.

Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

The bottom scraped and painted. Is now in good condition and in my opinion eligible to remain as Classed -

Committee's Minute

Liverpool July 29th - 1879

Character assigned

*A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. ✓ Survey held at Birkenhead Date, first Survey June 10th Last Survey July 5th 18 79

No. in on the Iron J "Rajpoot" Master J Andrew

Reg. Book. 45 Tonnage 1244 Built at Liverpool When built 1864-7

By whom built Vernon Owners J K Welch

Port belonging to London Destined Voyage Calcutta

If Surveyed Afloat or in Dry Dock In Great Flow dry dock, & afloat

Last Survey, No. 19750 Port of Iron Classed *A-1-11-77
ST Lir N-3-77

Present Condition of the
Decks

Good

Points Good

Waterways

"

Breasthooks and Stems " "

Comings

"

Transoms, Pointers, and Crutches " "

Upper Deck Beams & Fastenings

"

Timbers of the Frame at the Openings " "

Lower Deck Beams & Fastenings

"

Ditto ditto at other places " "

Planksheers

"

Keelsons " "

Sheerstrakes

"

Clamps and Shelves " "

Topsides

"

Ceiling " "

Wales

"

Rudder " "

Plank (Bottom) and Counter

"

Copper on Y.M. Cen When put on 64

Caulking of

Bottom, Deck, & Waterways Good

Engine Room Skylights Coal Bunkers, Openings, Lids, &c.

Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

The bottom scraped and painted. Is now in good condition and in my opinion eligible to remain as Classed -

Committee's Minute

Liverpool July 29th - 1879

Character assigned

*A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

Galatea
Rajpoot

26581.

