

REPORT of SURVEY for REPAIRS, &c.

No. *4616*

No. in Survey held at
Reg. Book.

on the

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm.

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

Last Survey, No.

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Placed on blocks in Dry Dock Bottom well cleaned and Coated with Paint.
Mizen Topmast, Topgallant mast, & all the after Yards sent down, New Lone Topmast, of Pitch Pine fitted, and the Vessel converted into a Barque

Condition of the

Beams & Fastenings

Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (on V.M.)

Caulking of

Bottom, Deck, & Waterways

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

The Vessel appears in good & efficient condition, eligible to remain as classed.

Change of Owners

The Amount of Entry Fee ...

Special ...

Certificate (if required)

to be sent as per margin...

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

received by me,

18 1879

£1.

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON486-0306

REPORT of STAFFORDSHIRE for REPAIRS &c.

Staffordshire

Blank lined form with faint mirrored text from the reverse side.

