

# ANNUAL SURVEYS.

No. 21639 Survey held at London Date, first Survey July 24<sup>th</sup> Last Survey July 24<sup>th</sup> 1879.  
 No. in on the SS Glenearn Master K. Gasson  
 Reg. Book. 452 Tonnage 1410 Built at Glasgow When built 1873 11.11  
 By whom built Sen & Glas Co Owners A. C. Gow & Co  
 Port belonging to Glasgow Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Green Dry Dock

Last Survey, No. 21639 Port of Iron  
 Present Condition of the  
 Decks good Treenails Rivets good  
 Waterways good Breasthooks and Stemson good  
 Comings good Transoms, Pointers, and Crutches good  
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good  
 Lower Deck Beams & Fastenings good Ditto ditto at other places good  
 Planksheers good Keelsons good  
 Sheerstrakes good Clamps and Shelves good  
 Topsides good Ceiling good  
 Wales good Rudder good  
 Plank (Bottom) and Counter good Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom Coated  
She is now in good condition and entitled to remain as classed.

Committee's Minute 1st August, 1879.  
 Character assigned 100 A  
T.B.W.

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 22506 Survey held at London Date, first Survey July 5 Last Survey July 8<sup>th</sup> 1879.  
 No. in on the SS Glencoe Master M. Fullard  
 Reg. Book. 38 Tonnage 1501 Built at Glasgow When built 1878 11.11  
 By whom built Sen & Glas Co Owners A. C. Gow & Co  
 Port belonging to Glasgow Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Green Dry Dock

Last Survey, No. 22506 Port of Iron  
 Present Condition of the  
 Decks good Treenails Rivets good  
 Waterways good Breasthooks and Stemson good  
 Comings good Transoms, Pointers, and Crutches good  
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good  
 Lower Deck Beams & Fastenings good Ditto ditto at other places good  
 Planksheers good Keelsons good  
 Sheerstrakes good Clamps and Shelves good  
 Topsides good Ceiling good  
 Wales good Rudder good  
 Plank (Bottom) and Counter good Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom Coated  
She is now in good condition and entitled to remain as classed.

Committee's Minute 1st August, 1879.  
 Character assigned 100 A  
T.B.W.

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18