

ANNUAL SURVEYS.

24135

Rev 1/8/79

No. 4252 Survey held at Dundee. Date 7th July. 1879.
 on the S. Ship "Silverhow." Master Baugail
 Tonnage 1221 Built at Whitehaven When built 1875 - 10 mo.
 By whom built Whitehaven Sh. Coy. Owners G. Nelson & Coy.
 Port belonging to Whitehaven Destined Voyage Shields to load for Bombay
 If Surveyed Afloat or in Dry Dock In Dry Dock with Tallow on board.

Last Survey, No. 21282 Port of Iron Classed 100A-1 578.

The present Condition of the

Decks	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Waterways	Suffers	Breasthooks and Stemson			Pumps	
Comings		Transoms, Pointers, and Crutches			Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places			Sails	
Planksheers		Keelsons where exposed			Anchors No. of 3B. 15. 2K.	
Sheerstrakes		Clamps and Shelves			Cables	
Topsides		Ceiling where exposed			Hawsers and Warps	
Wales		Rudder Good and efficient			Standing & Running Rigging	
Plank (Bottom) and Counter		Copper	Cum 12	When put on 1875		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good.

Vessel placed on blocks, Keel, bottom & sides examined, recoated bottom & sides.

This vessel is now in good and efficient condition and eligible in my opinion to remain as Classed.

Committee's Minute 5th August, 1879.

Character assigned

100A-1

TBW

J. L. Dimmette

Certificate (if required)

No. Survey held at Dundee. Date 7th July. 1879.
 on the S. Ship "Brambletye." Master Gibb
 Tonnage 1495 Built at Barrow. When built 1876 - 1 mo.
 By whom built Barrow Ship Building Coy. Owners W. R. Price.
 Port belonging to London. Destined Voyage Shields to load for Singapore.
 If Surveyed Afloat or in Dry Dock In Dry Dock with ballast on board.

Last Survey, No. 15878 Port of Iron Classed 100A-1 376.

The present Condition of the

Decks	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Waterways	Suffers	Breasthooks and Stemson			Pumps	
Comings		Transoms, Pointers, and Crutches			Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places			Sails	
Planksheers		Keelsons where exposed			Anchors No. of 3B. 15. 2K.	
Sheerstrakes		Clamps and Shelves			Cables	
Topsides		Ceiling where exposed			Hawsers and Warps	
Wales		Rudder Good and efficient			Standing & Running Rigging	
Plank (Bottom) and Counter		Copper	Cum 12	When put on 1876		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good.

Vessel placed on blocks, Keel, bottom & sides examined, recoated bottom & sides.

This vessel is now in good and efficient condition and eligible in my opinion to remain as Classed.

Committee's Minute 5th August, 1879.

Character assigned

100A-1

TBW

J. L. Dimmette

Certificate (if required)