

ANNUAL SURVEYS.

38330 24136

No. 796 Survey held at London Date, first Survey June 18th Last Survey July 29 1872
 No. in on the S Smyrna Master Jamieson
 Reg. Book. 796 Tonnage 1305 Built at Aberdeen When built 1876 10M
 By whom built Flood Owners G Thompson
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Blackwall Port by St

Last Survey, No. 20843 Port of Iron Classed 100 A-5.78
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of "
 Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom coated

She is now in good condition and entitled to remain as classed

Committee's Minute 5th August, 1872 Senhouse Martindale
 Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 297 Survey held at London Date, first Survey June 28 Last Survey July 23rd 1872
 No. in on the S Pericles Master J. Burgie
 Reg. Book. 297 Tonnage 1538 Built at Aberdeen When built 1877 7M
 By whom built Flood Owners G Thompson
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Blackwall Port by St

Last Survey, No. 21196 Port of Iron Classed 100 A-7.78
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of "
 Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom coated

She is now in good condition and entitled to remain as classed

Committee's Minute 5th August, 1872 Senhouse Martindale
 Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18