

Cause of Repairs to be clearly stated.


examined

Port.....*Sunderland*.....

Ship's Name.....*Pauline David*.....

Report on Ship No.....*12245*.....Sent *14<sup>th</sup> August*

Report on Machinery No.....*422*.....sent.....*do*.....



Lloyd's Register  
Foundation

IRON486-0385

*Now from ...*