

ANNUAL SURVEYS.

No. 4932 Survey held at Glasgow Date 23rd July to 1 Augth 1879
 on the S.S. Arklow Master Heffernan
 Tonnage 501 Built at Glasgow When built 1861-1862
 By whom built Stephen Owners Clyde Shipping Co.
 Port belonging to Glasgow Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock J & W Hendersons Dry Dock & Afloat

Last Survey, No. 21056 Port of Iron

Classed GOA

The present Condition of the

Decks	<u>Good</u>	<u>Transoms</u>	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	<u>Four</u>
Upper Deck Beams & Fastenings	"	Planks of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Planks at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of	<u>3 B. 1 L. 3 H.</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	<u>Good</u>
Topsides	"	Ceiling	"	"	Hawsers and Warps	<u>And</u>
Wales	"	Rudder	"	"	Standing and Running Rigging	<u>Sufficient</u>
Plate (Bottom) and Counter	"	Copper Cement When put on <u>1873</u>				
General Observations and Opinion,				Caulking of Bottom, Deck, and Waterways <u>Good</u>		

A few rivets in back of rudder renewed. Propeller refitted on shaft
 The bottom cleaned and painted. Is now in good condition in
 my opinion eligible to remain as classed.

Committee's Minute 8th August, 1879.

Character assigned GOA

Certificate (if required).

No. 4932 Survey held at Glasgow Date 5th July 1879
 on the S.S. Wiltshire Master James Robertson
 Tonnage 325 Built at Hartlepool When built 1876-1877
 By whom built Withy Owners Steel, Young & Co.
 Port belonging to London Destined Voyage East via Barrow
 If Surveyed Afloat or in Dry Dock J & W Hendersons & Co. Ship

Last Survey, No. 20667 Port of Iron

Classed GOA

The present Condition of the

Decks	<u>Good</u>	<u>Transoms</u>	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	<u>Three</u>
Upper Deck Beams & Fastenings	"	Planks of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Planks at other places	"	"	Sails	<u>1 Suit</u>
Planksheers	"	Keelsons	"	"	Anchors, No. of	<u>3 B. 1 L. 3 H.</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	<u>Good</u>
Topsides	"	Ceiling	"	"	Hawsers and Warps	<u>And</u>
Wales	"	Rudder	"	"	Standing and Running Rigging	<u>Sufficient</u>
Plate (Bottom) and Counter	"	Copper Cement When put on <u>1876</u>				
General Observations and Opinion,				Caulking of Bottom, Deck, and Waterways <u>Good</u>		

The bottom cleaned and coated with Black Varnish & Black Lead
 Is now in good condition in my opinion eligible to remain as Classed

Committee's Minute 8th August, 1879.

Character assigned GOA

Certificate (if required).