

ANNUAL SURVEYS.

No. 288 Survey held at London Date, first Survey July 22nd Last Survey July 29th 1879
 No. in on the SS Orwell Master J Broad
 Reg. Book. 288 Tonnage 444 Built at Newcastle When built 1864-71
 By whom built Palmer Owners J Fenwick & Sons
 Port belonging to London Destined Voyage Coasting (Coal Trade)
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 20944 Port of Iron Classed A 1-5.78
 Present Condition of the
 Decks Good Treenails Rivets (after renewal) Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Corten When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom is coated

She is now in good condition and entitled to remain as classed

Committee's Minute 8th August, 1879 Senhouse Martindale
 Character assigned A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 48 Survey held at London Date, first Survey July 15 Last Survey July 15th 1879
 No. in on the SS Taymouth Castle Master J Fulton
 Reg. Book. 48 Tonnage 1172 Built at Glasgow When built 1877-81
 By whom built Barclay Owners J Currie & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Green by St

Last Survey, No. 22495 Port of Iron Classed 100A 1-79
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Corten When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom is coated

She is now in good condition and entitled to remain as classed.

Committee's Minute 8th August, 1879 Senhouse Martindale
 Character assigned 100A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18