

ANNUAL SURVEYS. 214223

28348

No. 269 Survey held at London Date, first Survey July 4th Last Survey July 31st 1872
No. in on the SS Eldorado Master J. C. Kerr
Reg. Book. 269 Tonnage 2157 Built at Hull When built 1873-3M
By whom built Earles Owners A. Gray & E. S. Davies
Port belonging to Glasgow Destined Voyage India
If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 22183 Port of Iron

Classed

Years assigned. 100A 11.78
Character in Register Book.
SS Lin M-77

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	<u>"</u>	Condition, how ascertained	<u>From Bk</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	<u>"</u>	Sails	<u>Good</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	<u>"</u>	Anchors, No. of <u>3 No. 12 & 14 lbs</u>	<u>Good</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	<u>"</u>	Cables <u>Part on Bk</u>	<u>Good</u>
Wales	<u>"</u>	Rudder	<u>"</u>	<u>"</u>	Hawsers and Warps	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	<u>"</u>	<u>"</u>	Standing and Running Rigging	<u>"</u>
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	<u>"</u>		
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	<u>"</u>	Cargo and Main Hatchways	<u>Good</u>
General Observations, Opinion as to Class, &c.	<u>Bottom be coated</u>				Hatches	<u>Good</u>

She is now in good condition
and entitled to remain as classed

Committee's Minute

8th August, 1872Senhouse Martindale

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. 845 Survey held at London Date, first Survey July 17 Last Survey July 18th 1872
No. in on the SS City of London Master J. Patching
Reg. Book. 845 Tonnage 1816 Built at Glasgow When built 1863
By whom built For Owners W. H. Robt & Co.
Port belonging to Liverpool Destined Voyage "
If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 21625 Port of Iron

Classed

Years assigned. A 8.78
Character in Register Book.
SS Lin M-78

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	<u>"</u>	Condition, how ascertained	<u>From Bk</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	<u>"</u>	Sails	<u>Good</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	<u>"</u>	Anchors, No. of <u>3 No. 12 & 14 lbs</u>	<u>Good</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	<u>"</u>	Cables <u>Part on Bk</u>	<u>Good</u>
Wales	<u>"</u>	Rudder	<u>"</u>	<u>"</u>	Hawsers and Warps	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	<u>"</u>	<u>"</u>	Standing and Running Rigging	<u>"</u>
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	<u>"</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	<u>"</u>	Hatches	<u>Good</u>
General Observations, Opinion as to Class, &c.	<u>Bottom coated</u>					

She is now in good condition
and entitled to remain as classed

Committee's Minute

8th August, 1872Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Character assigned

Certificate (if required)

Paid

18