

No. 38383 Survey held at London Date, first Survey 7th August Last Survey 18th August 1879.

No. in on the Ship "Roslin Castle" Master R. Guthrie
Reg. Book. 609

Tonnage 1170. 1170. 1085 Built at Glasgow When built 1863 7th mo.

By whom built Napier Owners D. Currie & Co.

Port belonging to Liverpool Destined Voyage Cape Town

If Surveyed ~~Afloat~~ or in Dry Dock West India Traving Dock.

Last Survey, No. 19978 Port of Iron Classified 1.78 Character in Register Book. * A1

Present Condition of the

Decks	<u>Good</u>	<u>Timber</u>	<u>Rivets</u>	<u>Good</u>
Waterways	<u>do</u>	<u>Breasthooks and Stems</u>	<u>do</u>	<u>do</u>
Comings	<u>do</u>	<u>Transoms, Painters, and Crutches</u>	<u>do</u>	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	<u>Timbers of the Frame at the Openings</u>	<u>do</u>	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	<u>Ditto ditto at other places</u>	<u>not seen</u>	<u>do</u>
Planksheers	<u>do</u>	<u>Keelsons</u>	<u>do</u>	<u>do</u>
Sheerstrakes	<u>do</u>	<u>Clamps and Shells</u>	<u>do</u>	<u>do</u>
Topsides	<u>do</u>	<u>Ceiling</u>	<u>do</u>	<u>do</u>
Wales	<u>do</u>	<u>Rudder</u>	<u>do</u>	<u>do</u>
Planks (Bottom) and Counter	<u>do</u>	<u>Copper or F.M. Paint</u>	<u>When put on</u>	<u>now</u>
Engine Room Skylights	<u>do</u>	<u>Caulking of</u>	<u>Bottom, Deck, & Waterways</u>	<u>good</u>
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	<u>Scuppers</u>	<u>do</u>	<u>do</u>
General Observations, Opinion as to Class, &c.	<u>do</u>	<u>Cargo and Main Hatchways</u>	<u>good</u>	<u>Hatches</u>

General Observations, Opinion as to Class, &c.

Windlass renewed of Engl. Oak. - Bottom cleaned & repainted. -

Surveyed with ballast in hold under main hatch and part outward cargo between main hatch & after hatch. -

This vessel is in good condition & eligible in my opinion, to remain as classed. -

Committee's Minute 22nd August 1879.

Character assigned H. Paulsen.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18