

# ANNUAL SURVEYS.

No. 38385 Survey held at London Date, first Survey 22<sup>nd</sup> July Last Survey 25<sup>th</sup> July 1879.  
 No. in on the 13<sup>th</sup> "General Holt" Master Isaacs  
 Reg. Book. 163 Tonnage 733 Built at Sunderland When built 1877-10 mo  
 By whom built Austen Owners Morris  
 Port belonging to Aberystwyth Destined Voyage Upper Globe by Arch  
 If Surveyed Afloat or in Dry Dock Upper Globe by Arch

Last Survey, No. 19608 Port of Iron Classed 100 A.1.  
 Present Condition of the  
 Decks Good Treennails Rivets Good  
 Waterways — Breasthooks and Stems —  
 Comings — Transoms, Pointers, and Crutches —  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places —  
 Planksheers — Keelsons —  
 Sheerstrakes — Clamps and Shelves —  
 Topsides — Ceiling —  
 Wales — Rudder —  
 Plank (Bottom) and Counter — Copper or Y.M. Cent. When put on 1877  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Vessel examined with ballast in hold and where seen in good condition, and eligible to remain as classed.

Committee's Minute 22nd August, 1879.  
 Character assigned 100 A.1.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —

No. 814 Survey held at London Date, first Survey 15<sup>th</sup> Aug Last Survey 18<sup>th</sup> Aug 1879.  
 No. in on the 12<sup>th</sup> "Loweswater" Master E. Lewis  
 Reg. Book. 814 Tonnage 603 Built at Whitehaven When built 1876-11 mo  
 By whom built Wh. Sh. B. Co Owners Jackson & Metcalf.  
 Port belonging to Liverpool Destined Voyage Queensland  
 If Surveyed Afloat or in Dry Dock Bull Head dry dock &c.

Last Survey, No. 17529 Port of Iron Classed 100 A.1.  
 Present Condition of the  
 Decks Good Treennails Rivets Good  
 Waterways — Breasthooks and Stems —  
 Comings — Transoms, Pointers, and Crutches —  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places —  
 Planksheers — Keelsons —  
 Sheerstrakes — Clamps and Shelves —  
 Topsides — Ceiling —  
 Wales — Rudder —  
 Plank (Bottom) and Counter — Copper or Y.M. Cent. When put on 1876  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Vessel examined with ballast in lower hold and where seen found in good condition, and in my opinion eligible to remain as classed.

Committee's Minute 22nd August, 1879.  
 Character assigned 100 A.1.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —