

Recd 26/8/79

# ANNUAL SURVEYS.

24499

No. 26639 Survey held at Liverpool Date, first Survey July 21<sup>st</sup> Last Survey July 24<sup>th</sup> 1879  
No. in on the Iron Bk "Sola" Master J. McRae  
Reg. Book. 814 Tonnage 653 Built at Glasgow When built 1876-8  
By whom built Elder Owners J. Kelso  
Port belonging to Glasgow Destined Voyage Glasgow  
If Surveyed Afloat or in Dry Dock Brunswick dry dock

Last Survey, No. 21648 Port of Glasgow

Classed 100 A. 1. 0. 70

Present Condition of the  
Decks Good Iron Rivets Good  
Waterways " Breasthooks and Stems "  
Comings " Transoms, Poppers, and Crutches "  
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
Lower Deck Beams & Fastenings " Ditto ditto at other places "  
Planksheers " Keelsons "  
Sheerstrakes " Clamps and Shelves "  
Topsides " Ceiling "  
Wales " Rudder "  
Plates (Bottom) and Counter " Copper or Y.M. Cen When put on 76  
Caulking of Bottom, Deck, & Waterways Good  
Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c. Windlass and Capstan Good & efficient  
Pumps " Boats "  
Masts, Yards, &c. " Condition, how ascertained Seen from deck  
Sails " Anchors, No. of Good  
Cables " Hawseers and Warps "  
Standing and Running Rigging efficient

The bottom scraped and painted. This vessel is now in good condition and in my opinion eligible to remain as Classed -

Committee's Minute Liverpool Sep<sup>r</sup> 5<sup>th</sup> 1879  
Character assigned 100 A. 1.

E. Wheeler  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) " Paid " 18 "

No. ✓ Survey held at Birkenhead Date, first Survey July 17<sup>th</sup> Last Survey Aug 13<sup>th</sup> 1879  
No. in on the Iron Bk "Cannon Forest" Master Marshall  
Reg. Book. 29 Tonnage 1060 Built at Port-Glasgow When built 1878-1 mo  
By whom built Russell Owners J. C. King & Co  
Port belonging to Glasgow Destined Voyage India  
If Surveyed Afloat or in Dry Dock Afloat in Great Blower dry dock

Last Survey, No. 22145 Port of Glasgow

Classed 100 A. 1. 0. 70

Present Condition of the  
Decks Good Iron Rivets Good  
Waterways " Breasthooks and Stems "  
Comings " Transoms, Poppers, and Crutches "  
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
Lower Deck Beams & Fastenings " Ditto ditto at other places Not seen  
Planksheers " Keelsons Good  
Sheerstrakes " Clamps and Shelves "  
Topsides " Ceiling "  
Wales " Rudder "  
Plates (Bottom) and Counter " Copper or Y.M. Cen When put on 70  
Caulking of Bottom, Deck, & Waterways Good  
Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c. Windlass and Capstan Good & efficient  
Pumps " Boats "  
Masts, Yards, &c. " Condition, how ascertained Seen from deck  
Sails " Anchors, No. of Good  
Cables " Hawseers and Warps "  
Standing and Running Rigging efficient

The bottom scraped and painted - This vessel is now in good condition and in my opinion eligible to remain as Classed -

Committee's Minute Liverpool Sep<sup>r</sup> 5<sup>th</sup> 1879  
Character assigned 100 A. 1.

E. Wheeler  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) " Paid " 18 "

2172

Isola  
badzon Forest  
26639



© 2019

Lloyd's Register  
Foundation