

ANNUAL SURVEYS.

No. 2666² Survey held at Liverpool Date, first Survey July 3rd Last Survey July 10th 1878
 No. in on the Iron S. "Hippolyta" Master J. J. Capen
 Reg. Book. 492 Tonnage 853 Built at Port Glasgow When built 1856
 By whom built James & Sons Owners J. Heap & Sons
 Port belonging to Liverpool Destined Voyage Rangoon
 If Surveyed Afloat or in Dry Dock Afloat in Queen's dry dock

Last Survey, No. 19407 Port of Liverpool
 Present Condition of the
 Decks Good Reels Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Clutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper on Y.M. Cen When put on 60th
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good

The bottom scraped and painted - This vessel is now in good condition and in my opinion eligible to remain as Classed.

Committee's Minute Liverpool Sep^r 23rd 1879
 Character assigned *A1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid " 18

No. — Survey held at Birkenhead Date, first Survey Aug^t 15th Last Survey Aug^t 16th 1879
 No. in on the Iron S. S. "Bothal" Master Pattison
 Reg. Book. 623 Tonnage 1220 Built at Newcastle When built 1870 - 3^{mo}
 By whom built Teasdale Owners St. James, Bell & Co
 Port belonging to Newcastle Destined Voyage Barrage
 If Surveyed Afloat or in Dry Dock In Messrs. Clavers dry dock

Last Survey, No. 20489 Port of Liverpool
 Present Condition of the
 Decks Good Reels Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Clutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper on Y.M. Cen When put on 70th
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good

Propeller renewed and bottom painted. This vessel is now in good condition and in my opinion eligible to remain as Classed.

Committee's Minute Liverpool Sep^r 23rd 1879
 Character assigned 100 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid " 18

Hippoclepta

Bothral

ss

26662



© 2019

Lloyd's Register
Foundation