

ANNUAL SURVEYS.

No. 4260 Survey held at West Hartlepool Date, first Survey 15 Sept (Received at London Office, 18/9/79)
 No. in on the Sw. S. "Breeze" Last Survey 16 Sept 1879
 Reg. Book. 643 Tonnage 1010 Built at Hartlepool Master W. Holman
673 By whom built Withy Owners T. Appleby & Co
 Port belonging to West Hartlepool Destined Voyage West Hartlepool to Malta
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 22475 Port of Iron Classed 90 A1
 Present Condition of the Decks Good Treenails Plink Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Plank sheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Good When put on Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Now done bottom cleaned down & coated with paint & black varnish
Is now in a good & efficient state, fit for the safe conveyance of dry & perishable goods to & from all parts of the World, & may in my opinion remain as now
Classed 90 A1
L.S. Hpl. No. 1-79

Committee's Minute 19th September, 1879. L. P. Gladstone
 Character assigned 90 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
W. D. P. Certificate (if required) Paid 1879

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Plank sheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18