

18/9/79

24510

ANNUAL SURVEYS.

(Received at London Office, 19th September 1879)

No. 38482 Survey held at London Date, first Survey Aug 22 Last Survey Sept 18 1879
 No. in on the S Thersford Master M. Catter
 Reg. Book. 377 Tonnage 1440 Built at Glasgow When built 1865 7M
 By whom built Elder Owners Merchant Ship Co
 Port belonging to London Destined Voyage Sancti Spiritus
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 21483 Port of Iron Classed A1-8.78
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches ✓
 General Observations, Opinion as to Class, &c. Bottom & coated.

She is now in good condition and entitled to remain as classed.

Committee's Minute 23rd September, 1879. Senhouse Martinade.
 Character assigned T.B.W. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

No. Survey held at London Date, first Survey Aug 14 Last Survey Aug 17 1879
 No. in on the S Ben Nevis Master Mackie
 Reg. Book. 283 Tonnage 1461 Built at Glasgow When built 1868 6M
 By whom built Burdaz Owners Watson Bros.
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Greens Dock

Last Survey, No. 21482 Port of Iron Classed A1-7.78
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches ✓
 General Observations, Opinion as to Class, &c. Bottom & coated.

She is now in good condition and entitled to remain as classed.

Committee's Minute 23rd September, 1879. Senhouse Martinade.
 Character assigned T.B.W. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

IRON 487-0362